

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403653141

Date Received:  
01/12/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
-		<a href="mailto:rbucogccinspectionreports@chevron.onmicrosoft.com">rbucogccinspectionreports@chevron.onmicrosoft.com</a>

COGCC INSPECTION SUMMARY:

FIR Document Number: 708200721

Inspection Date: 11/29/2023

FIR Submit Date: 12/05/2023

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 319123

Location Name: GOLD-65N66W Number: 22SESW County: \_\_\_\_\_

Qtrqtr: SESW Sec: 22 Twp: 5N Range: 66W Meridian: 6

Latitude: 40.379630 Longitude: -104.768150

FACILITY - API Number: 05-123-00 Facility ID: 319123

Facility Name: GOLD-65N66W Number: 22SESW

Qtrqtr: SESW Sec: 22 Twp: 5N Range: 66W Meridian: 6

Latitude: 40.379630 Longitude: -104.768150

CORRECTIVE ACTIONS:

1  CA# 188894

Corrective Action: Comply with Rule 606 and remove all trash from location. The location will remain out of compliance until the corrective action has been resolved.

Date: 11/29/2023

Response: CA COMPLETED

Date of Completion: 12/11/2023

Operator Comment: Complied with rule 605.g. please see attached picture

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

2  CA# 188895

Corrective Action: Install sign to comply with Rule 605.g. The location will remain out of compliance until the corrective action has been resolved.

Date: 11/29/2023

Response: CA COMPLETED

Date of Completion: 12/28/2023

Operator Comment: Complied with rule 606 please see attached picture

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Complied with rule 605.g. and rule 606 please see attached pictures. This FIR Resolution encompasses corrective action 1 and 2

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Isaiah Flores

Signed: \_\_\_\_\_

Title: HSE

Date: 1/12/2024 10:53:00 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403653141	FIR RESOLUTION SUBMITTED
403653169	pic
403653172	pic
403653174	pic
403653175	pic
403653177	pic
403653196	pic
403653197	pic

Total Attach: 8 Files