

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403658484

Date Received:

01/18/2024

## FIR RESOLUTION FORM

Overall Status: FRQ

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

0 CA Completed

1 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: 501 N DIVISION BLVD

City: PLATTEVILLE State: CO Zip: 80651

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Binschus, Chris

chris.binschus@state.co.us

COGCCInspections@Oxy.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 713900263

Inspection Date: 01/11/2024

FIR Submit Date: 01/17/2024

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: KERR MCGEE OIL & GAS ONSHORE LP

Company Number: 47120

Address: P O BOX 173779

City: DENVER

State: CO

Zip: 80217-3779

### LOCATION - Location ID: 328213

Location Name: BELL-63N66W

Number: 12NENW

County: WELD

Qtrqtr: NENW

Sec: 12

Twp: 3N

Range: 66W

Meridian: 6

Latitude: 40.245570

Longitude: -104.727640

### FACILITY - API Number: 05-123-

-00

Facility ID: 247907

Facility Name: BELL

Number: L12-3

Qtrqtr: NENW

Sec: 12

Twp: 3N

Range: 66W

Meridian: 6

Latitude: 40.245570

Longitude: -104.727640

### CORRECTIVE ACTIONS:

1 ☒ CA# 190081

Corrective Action: Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

Date: 01/11/2024

Response: FACTUAL REVIEW REQUEST

Basis for Review: Action requested was already completed prior to the inspection

Operator Comment: See attached work request completion reports for seasonal maintenance performed in May, August, and September of 2023. Inspection doc #713900263 performed outside of warm and/or cool growing seasons. Site is routinely mowed and inter-seeded with an approved mix. Land is heavily grazed and hinders reclamation progress and timeline. OXY will continue to monitor and maintain seasonally until site has successfully achieved Rule 1004 requirements.

COGCC Decision: **Not Approved**

COGCC Representative: Based on observations in the field, though additional seeding activities within the eastern areas of the Location was apparent, Reclamation Specialist did not observe any evidence that additional reclamation work had been performed within the disturbed areas on the west end of the Location.

Additionally, documentation provided by Operator attached only shows work performed within the areas of the Location east of the access road.

No additional work will be required within the eastern disturbance where recent reclamation work is apparent; however, the corrective action requiring reclamation work will remain applicable for the western areas of the Location.

If it is determined grazing pressure is hindering reclamation as indicated by Operator, Operator shall implement mitigating measures in order to minimize or prevent grazing pressure until Location receives a passing final reclamation inspection; It is the Operator's responsibility to ensure that the Location remains in compliance and progresses towards ECMC 1004 standards.

COGCC Supervisor: Based on observations in the field, though additional seeding activities within the eastern areas of the Location was apparent, Reclamation Specialist did not observe any evidence that additional reclamation work had been performed within the disturbed areas on the west end of the Location.

Additionally, documentation provided by Operator attached only shows work performed within the areas of the Location east of the access road.

No additional work will be required within the eastern disturbance where recent reclamation work is apparent; however, the corrective action requiring reclamation work will remain applicable for the western areas of the Location.

If it is determined grazing pressure is hindering reclamation as indicated by Operator, Operator shall implement mitigating measures in order to minimize or prevent grazing pressure until Location receives a passing final reclamation inspection; It is the Operator's responsibility to ensure that the Location remains in compliance and progresses towards ECMC 1004 standards.

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Austin Lee

Signed:

Title: Advisor HSE Environ Ops

Date: 1/18/2024 9:35:50 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403658484	FIR RESOLUTION SUBMITTED
403658490	WRCR May 2023
403658491	WRCR August 2023
403658492	WRCR September 2023

Total Attach: 4 Files