

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403656057

Date Received:

01/16/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 5 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Luke Kelly

Phone

970-939-6353

Email

lkelly@civiresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 713900195

Inspection Date: 12/15/2023

FIR Submit Date: 12/28/2023

FIR Status: _____

Inspected Operator Information:

Company Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Company Number: 8960

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 429060

Location Name: North Platte Number: I-24 Pad County: _____

Qtrqr: SESW Sec: 24 Twp: 5N Range: 63W Meridian: 6

Latitude: 40.378861 Longitude: -104.387961

FACILITY - API Number: 05-123-00 Facility ID: 429060

Facility Name: North Platte Number: I-24 Pad

Qtrqr: SESW Sec: 24 Twp: 5N Range: 63W Meridian: 6

Latitude: 40.378861 Longitude: -104.387961

CORRECTIVE ACTIONS:

1 ☒ CA# 189626

Corrective Action: Replace tank labels per Rule 605.

Date: 12/15/2023

Response: CA COMPLETED

Date of Completion: 01/15/2024

Operator Comment: Operator appropriately updated the tank labels to comply with Rule 605.

COGCC Decision: Approved via an AMI

COGCC Representative: Approved via an AMI of this FIR resolution acknowledges the document and attachments were received. Based on the attached photos, Operator has completed the corrective action. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

2 ☒ CA# 189627

Corrective Action: Comply with Rule 606 to remove weed debris.

Date: 12/15/2023

Response: CA COMPLETED

Date of Completion: 01/12/2024

Operator Comment: Operator has appropriately addressed and cleared tumbleweeds and weed debris from the location to assist with keeping to location clean and preventing the spread of weeds. Operator will continue to monitor and manage weeds on location to comply with Rule 606.

COGCC Decision: Approved via an AMI

COGCC Representative: Approved via an AMI of this FIR resolution acknowledges the document and attachments were received. Based on the attached photos, Operator has completed the corrective action. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

3 ☒ CA# 189628

Corrective Action: Best management practices to prevent weed establishment shall be implemented. Control, manage, and prevent weedy, annual vegetation on all topsoil stockpiles. If reseeding is an option for long-term protection and stabilization of topsoil, then the next favorable seeding opportunity shall be conducted.

Date: 12/15/2023

Response: CA COMPLETED

Date of Completion: 01/12/2024

Operator Comment: Operator has appropriately addressed the identified issues pertaining to the spread of weeds and weed debris throughout the location. The area has now been properly cleared of weed debris and reseeded to assist with establishing new vegetation.

COGCC Decision: Approved via an AMI

COGCC Representative: Approved via an AMI of this FIR resolution acknowledges the document and attachments were received. Based on the attached photos, Operator has completed the corrective action. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

4 ☒ CA# 189629

Corrective Action: Perform reclamation in accordance with Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until the location meets Rule 1003 standards, including stormwater and weed management.

Date: 12/15/2023

Response: CA COMPLETED

Date of Completion: 01/12/2024

Operator Comment: Operator adequately addressed identified areas of issue to assist with restoring and revegetating the location appropriately comply with Rule 1003.

COGCC Decision: Approved via an AMI

COGCC Representative: Approved via an AMI of this FIR resolution acknowledges the document and attachments were received. Based on the attached photos, Operator has completed the corrective action. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed:

Title: Sr Regulatory Analyst

Date: 1/16/2024 6:29:40 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403656057	FIR RESOLUTION SUBMITTED
403656714	Inspection Resolution Report

Total Attach: 2 Files