

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402298512

Date Received:

01/29/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Victoria Dizghinjili

303-825-4822

vdizghinjili@kpk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 687400737

Inspection Date: 01/07/2020

FIR Submit Date: 01/07/2020

FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 319877

Location Name: BEISEL UNIT-61S68W Number: 1SWNE County: _____

Qtrqr: SWNE Sec: 1 Twp: 1S Range: 68W Meridian: 6

Latitude: 39.996678 Longitude: -104.946144

FACILITY - API Number: 05-001- -00 Facility ID: 319877

Facility Name: BEISEL UNIT-61S68W Number: 1SWNE

Qtrqr: SWNE Sec: 1 Twp: 1S Range: 68W Meridian: 6

Latitude: 39.996678 Longitude: -104.946144

CORRECTIVE ACTIONS:

1 ☒ CA# 135739

Corrective Action: Location is within a designated setback location, bullplug or cap all loadlines per Rule 604.c.(2)O.

Date: 01/13/2020

Response: CA COMPLETED

Date of Completion: 01/13/2020

Operator Comment: Bullplug on loadout valve has been installed. Please see attached pictures.

COGCC Decision: Approved via an AMI

COGCC Representative:			
2	✔	CA# 135740	
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: <u>02/07/2020</u>
Response:	<u>CA COMPLETED</u>		Date of Completion: <u>01/22/2020</u>
Operator Comment:	All berms at location have been repaired. Stained soil next to berm near load out line has been removed. Please see attached pictures.		
COGCC Decision:	<u>Approved via an AMI</u>		
COGCC Representative:			

<u>OPERATOR COMMENT AND SUBMITTAL</u>	
Comment:	
<p>I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.</p> <p>Print Name: <u>Victoria Dizghinjili</u> Signed: _____</p> <p>Title: <u>Engineering Test</u> Date: <u>1/29/2020 3:59:50 PM</u></p>	

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402298512	FIR RESOLUTION SUBMITTED
402298550	Berms PIC2
402298560	Well PIC1
402298566	Completed CA PIC3

Total Attach: 4 Files