

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/23/2024

Submitted Date:

01/26/2024

Document Number:

713600656

FIELD INSPECTION FORM

Loc ID 322227 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 44390
Name of Operator: JAVERNICK OIL
Address: 3040 E MAIN
City: CANON CITY State: CO Zip: 81212

Findings:

- 8 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Javernick, James		javernick1@gmail.com	
,		dnr_cogccenforcement@state.co.us	
Javernick, Salene		salenej@gmail.com	
Sanchez, Chris		chris.sanchez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210044	WELL	SI	11/01/2022	OW	043-06122	SLANOVICH 32-1	RI

General Comment:

[This is a follow up of the previous reclamation inspections and in regard to NOAV #403595832.](#)
[The corrective actions of the previous inspections have not been completed.](#)
[See attached photos and additional details within this report.](#)

Location

Lease Road:			
Type	Access		
comment:	The lease road is now accessible.		
Corrective Action:		Date:	

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	There are equipment storage trailers that remain on location that need to be removed. Previous corrective action was not completed.		
Corrective Action:	Comply with Rule 606	Date:	06/07/2023

Overall Good:

Spills:

Type	Area	Volume			
Crude Oil	Tank				
Comment:	There was a dripping leak observed at the backside of the tank valve. The dripping leak was no longer observed and the tank appears to be empty. It is uncertain if the spill at the backside of the tank was properly cleaned up or if the tank was repaired, therefore corrective action remains. There was oil stained soils found at the front side of the tank that needs to be cleaned up.				
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. Conduct maintenance on equipment, cleanup stained material and review self inspection processes.			Date:	11/11/2022

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat) (Long)
Drill Cuttings	Piles		
Comment	The cuttings pile still remains on location. There is a berm installed around the cuttings pile along with a plastic liner for containment. There are signs where gray cuttings have washed across the pad surface and have not been cleaned up. It does not appear a form 27 has been submitted. Previous corrective action has not been completed.		
Corrective Action	Comply with Rule 905. Immediately clean up. Implement or modify BMPs for improved material handling and spill prevention. Additionally, Operator shall file a Form 27 for the remediation of the Drill Cuttings per Rule 905.g.		Date: 01/24/2023

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Fail

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? Fail

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? Fail Production areas stabilized ? Fail
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Fail
 Production areas have been stabilized? Fail Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Fail Recontoured Fail 80% Revegetation Fail

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? F

Comment The vegetation is now dormant but undesirable and noxious weeds were previously observed. There did not appear to be any weed control performed since previous inspection. The access road and location are not stabilized and disturbed areas are not reclaimed. The soils that were pushed out during drilling operations have not been replaced and reclaimed. Previous corrective action was not completed.

Corrective Action Comply with 1003 Rules

Date 07/13/2023

Overall Interim Reclamation Fail

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment: Operator should consider plugging and abandoning the well if it is no longer capable of production.

Corrective Action: _____	Date _____
Overall Final Reclamation <input type="checkbox"/>	Well Release on Active Location <input type="checkbox"/>
	Multi-Well Location <input type="checkbox"/>

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There have been erosion repairs performed along the access road and culverts were installed at the drainage crossing. It does not appear the two culverts are adequately sized or installed to handle storm events. There has been rock and debris pushed up along the drainage across the road to the northwest which could restrict drainage flow (photo 2). There are loose sandy soils along the road that are not stabilized. There are still signs of erosion at the location. The cut and fill slopes are not stabilized and existing BMP's are insufficient. BMP's must be implemented in accordance with good engineering practice and must be maintained. Corrective action will remain out of compliance until completed.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)

Date: 12/30/2022

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713600657	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6408538