

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/30/2024

Submitted Date:

01/30/2024

Document Number:

702502325**FIELD INSPECTION FORM**Loc ID 315978 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10775

Name of Operator: KT RESOURCES LLC

Address: 3381 WESTBROOK LANE

City: HIGHLANDS State: CO Zip: 80129

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

3 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
Gale, Tony	(303) 886-8733	tony@kt-res.com	
Baumgras, Dan	(307) 321-3299	Dan@KT-Res.com	
Adams, Karen	(303) 886-8733	adams@kt-res.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231846	WELL	SI	10/01/2020	GW	103-09517	MOBIL-JACOBS 1-3	SI

General Comment:**ECMC Inspection Report Summary**

On Tuesday, 01/30/2024, Inspector Kirby Burchett, conducted a follow up field inspection at KT Resources LLC on the Mobil-Jacobs 1-3 well, Location #315978, in Rio Blanco County, Colorado.

This location is within or in close proximity to Parks and Wildlife (CPW) District with High Priority, NSO, Density, and Other Consultation Habitats.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Insp. #702501170 on 4/20/23. Original due dates remain on unresolved Corrective Actions:

1. API and emergency numbers not displayed on wellhead sign. (API Resolved)
(No emergency number on location)
2. Gas meter calibration card not visibly displayed. (Unresolved)
3. Well is overdue for Mechanical Integrity Test. (Unresolved)
4. Insufficient Stormwater BMPs. (Unresolved)

Refer to Inspection Photos for observed compliance issues.

While there during normal production operations the following compliance issues were observed:

1. Gas meter calibration out of compliance. Card buried inside meter box.
 2. No emergency number on well sign. No entrance sign. No tank battery.
- Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	No tank battery. Well sign lacks required information		
Corrective Action:	When no associated Tank battery is present at the Oil and Gas Location, the following additional information is required on the Well sign: Name of the Operator; Telephone number at which the Operator can be reached at all times; Telephone number for local emergency services (911 where available); and The public road used to access the Well.	Date:	05/22/2023

Emergency Contact Number:

Comment:	No emergency contact information addressed under Signs/Marker: Wellhead	Date:	
Corrective Action:			

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Rail		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Meter run. Rail fence.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Wellhead		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	No visible display of calibration card.		
Corrective Action:	The Operator will conspicuously post and maintain the date of the last meter calibration in a legible condition at each meter at all times.	Date:	05/08/2023

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	231846	Type:	WELL	API Number:	103-09517	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: Last Production - September 2020 Well is overdue for Mechanical Integrity Test (MIT). MIT requires 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well.									
Corrective Action: Perform successful mechanical integrity test. If a successful MIT cannot be performed within 30 day CA time the well must be plugged within 3 months.									
Date: 05/21/2023									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Limited Stormwater inspection due to snow.

Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702502326	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6413013