

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403660198

Date Received:

01/19/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 3 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Romana Cowden

Phone

720-951-5895

Email

COGCC.inspections@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 702502263

Inspection Date: 01/03/2024

FIR Submit Date: 01/03/2024

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 316338

Location Name: LITTLE HILLS FEDERAL-61N97W Number: 35NWNE County: RIO BLANCO

Qtrqr: NWNE Sec: 35 Twp: 1N Range: 97W Meridian: 6

Latitude: 40.015760 Longitude: -108.244800

FACILITY - API Number: 05-103-00 Facility ID: 267008

Facility Name: LITTLE HILLS FEDERAL Number: F31X-35G

Qtrqr: NWNE Sec: 35 Twp: 1N Range: 97W Meridian: 6

Latitude: 40.015760 Longitude: -108.244800

CORRECTIVE ACTIONS:

3 CA# 189782

Corrective Action: Install sign at locked entrance gate.
The Location Entrance sign will identify: The Well name; The Commission's Location identification number (ID #); The Operator's telephone number where it may be reached at all times; and the Telephone number(s) for local emergency services (911 where available).

Date: 02/03/2024

Response: CA COMPLETED

Date of Completion: 01/03/2024

Operator Comment: No rule cited; Rule 605 does not require a sign at the gate.

COGCC Decision: **Not Approved**

COGCC Representative: Location entrance signs enable First Responders to effectively identify hazards and mitigate risks in an emergency. When access is restricted along lease roads the lack of location entrance signs at lease road entrance delays emergency response personnel.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed: _____

Title: EHS

Date: 1/19/2024 8:44:58 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

| | |
|-----------|--------------------------|
| 403660198 | FIR RESOLUTION SUBMITTED |
|-----------|--------------------------|

Total Attach: 1 Files