

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/02/2024

Submitted Date:

02/05/2024

Document Number:

697602252**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Ahmadian, Alexander 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Anderson, Laurel		laurel.anderson@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	
Peterson, John		jpeterson@kpk.com	KPK environmental
Watzman, Ross	303-825-4822	rwatzman@kpk.com	
, KPK		cogcc@kpk.com	All Inspections
Brown, Kari		kari.oakman@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
485797	SPILL OR RELEASE	AC	01/22/2024		-	Jillson #2 Bullplug Hist. Release	EI

General Comment:

ECMC environmental inspection in response to Spill ID 485797. Any corrective actions from previous inspections that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection. KPK personnel had sampled the excavation before ECMC personnel had arrived.

Photos attached to document site conditions.

Inspected Facilities									
Facility ID:	485797	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

--

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Other	Inadequate		
Comment	A supposedly clean stockpile was left on location. If the stockpile was scraped from the surrounding area, then stockpile will be deemed as impacted.			
Corrective Action	Per CA Doc #714300023: E&P Waste not properly stored, handled, transported, treated, recycled, or dispose per Rule 905. Prior to spill closer Operator will collect a soil sample from underneath the observed soil stockpile area.			Date: 01/31/2024

Spill/Remediation:

Comment:	Spill ID 485797 remains open. Sampling activities occurred 2/2/2024			
Corrective Action:	Pursuant to Rule 912.b.(6) Operator is required to submit a Form 19 Supplemental Report for the associated spill within 90 days of the spill date requesting closure pursuant to Rule 913.h and supported by adequate documentation to demonstrate that the Spill or Release has been fully cleaned up and complies with Table 915-1; or A Form 27 if any of the criteria listed in Rules 912.b.(6).B.i±iii apply. If Remediation will continue under an approved Form 27, the Operator will also submit a Form 19± Supplemental which requests closure of the Spill or Release and includes the Remediation project number assigned by the Director.			Date: 04/01/2024

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____

Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697602253	Photolog	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6419337