

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/30/2024

Submitted Date:

02/06/2024

Document Number:

710500166**FIELD INSPECTION FORM**Loc ID 321098 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10330Name of Operator: INVESTMENT EQUIPMENT LLCAddress: 558 CASTLE PINES PKWY UNIT B-4City: CASTLE PINES State: CO Zip: 80108**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Highberger, Kathryn		kathrynhighberger@gmail.com	
Costa, Ryan		ryan.costa@state.co.us	
Bongers, Brent		bbongers@impetroresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206034	WELL	PA	11/19/2020	OW	009-06450	TANNER SEC REC UNIT 501	EG
485834	SPILL OR RELEASE	AC	01/23/2024		-	TANNER SEC REC UNIT-635S46W/11NENE	EI

General Comment:

This is a follow-up Environmental Inspection for the Tanner "E" 1 P&A well location API # 05-009-06450 Located in Baca County Colorado.

Location				
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date: _____
Corrective Action:				
Good Housekeeping:				
Type	OTHER			
Comment:	Impacted soils remain on the location			
Corrective Action:				Date:
Type	UNUSED EQUIPMENT			
Comment:	Unused equipment is still present on location			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	206034	Type:	WELL	API Number:	009-06450	Status:	PA	Insp. Status:	EG
Facility ID:	485834	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

Environmental**Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: _____

Comment: Areas of impacts are still present on the location and soil piles remain. Additionally, the Impacts to native soils adjacent to the location are still present. Operator has filed a Form 19 for the site investigation and cleanup of affected soils. Spill ID # 485834

Corrective Action: Pursuant to Rule 912.b.(6) Operator is required to submit a Form 19 Supplemental Report for the associated spill within 90 days of the spill date requesting closure pursuant to Rule 913.h and supported by adequate documentation to demonstrate that the Spill or Release has been fully cleaned up and complies with Table 915-1; or a Form 27 if any of the criteria listed in Rules 912.b.(6).B.i-iii apply. If Remediation will continue under an approved Form 27, the Operator will also submit a Form 19 – Supplemental which requests closure of the Spill or Release and includes the Remediation project number assigned by the Director. Form 19 Supplemental is due by April 7, 2024.

Date: 04/07/2024

Reportable: _____

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Waste Management:

Type Management Condition GPS (Lat) (Long)

Oily Soil	Piles	Inadequate			
Comment	Stockpiles of soil are still present on the location. At the time of inspection, it was observed some larger dirt clods impacted by oily material were removed.				
Corrective Action					Date: _____

Spill/Remediation:

Comment: _____

Corrective Action: _____ Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

COGCC Comments

Comment	User	Date
Impacted soils remain on the location Cleanup soils and manage per Rule 905	sanchezcc	02/06/2024
Unused equipment is still present on location Comply with 1004 Rules.	sanchezcc	02/06/2024
Operator has filed a Form 19 for the site investigation and cleanup of affected soils. Spill ID # 48583	sanchezcc	02/06/2024
Stockpiles of soil are still present on the location	sanchezcc	02/06/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500167	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6420772