

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/06/2024

Submitted Date:

02/06/2024

Document Number:

702502361

FIELD INSPECTION FORM

Loc ID 314427 Inspector Name: Burchett, Kirby On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

OGCC Operator Number: 10779
Name of Operator: SCOUT ENERGY MANAGEMENT LLC
Address: 13800 MONTFORT DRIVE SUITE 100
City: DALLAS State: TX Zip: 75240

Contact Information:

Contact Name	Phone	Email	Comment
Sanford, Anita	(970) 551-8313	Anita.Sanford@scoutep.com	
Patterson, Chris		Chris.Patterson@scoutep.com	
Regulatory, Rangely		RangelyRegulatory@scoutep.com	
Johnson, Mike		Mike.Johnson@scoutep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228711	WELL	PR	01/01/2023	OW	103-05683	FEE 68A	PR

General Comment:

[ECMC Inspection Report Summary](#)

On Tuesday, 02/06/2024, Inspector Kirby Burchett, conducted a routine field inspection at Scout Energy Management LLC on the Fee 68A well, Location #314427, in Rio Blanco County, Colorado.

This location is within or in close proximity to Parks and Wildlife (CPW) District and High Priority Habitat area with NSO and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal production operations no compliance issues were observed:

No follow up inspection is required.

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	970-675-3799 or 911		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

	Type PUMP JACK		
Comment:			
Corrective Action:		Date:	

Equipment:

					corrective date
Type: Bradenhead	# 1				
Comment:					
Corrective Action:		Date:			
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:		Date:			
Type: Pump Jack	# 1				
Comment:					
Corrective Action:		Date:			

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 228711 Type: WELL API Number: 103-05683 Status: PR Insp. Status: PR

Producing Well

Comment: [November 2023 Production report](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Berms						

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702502362	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6420824