

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403669871

Date Received:

02/05/2024

## FIR RESOLUTION FORM

Overall Status: CAC

### CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 52530

Name of Operator: MAGPIE OPERATING INC

Address: 2707 SOUTH COUNTY RD 11

City: LOVELAND State: CO Zip: 80537

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name

Phone

Email

Jody Kost

719-429-1434

magpieoil2@yahoo.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 697602221

Inspection Date: 11/28/2023

FIR Submit Date: 11/30/2023

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: MAGPIE OPERATING INC

Company Number: 52530

Address: 2707 SOUTH COUNTY RD 11

City: LOVELAND State: CO Zip: 80537

### LOCATION - Location ID: 307137

Location Name: MEHAFFEY-65N68W Number: 30NWNW County: \_\_\_\_\_

Qtrqr: NWN Sec: 30 Twp: 5N Range: 68W Meridian: 6  
W

Latitude: 40.376693 Longitude: -105.056970

### FACILITY - API Number: 05-069- -00 Facility ID: 307137

Facility Name: MEHAFFEY-65N68W Number: 30NWNW

Qtrqr: NWN Sec: 30 Twp: 5N Range: 68W Meridian: 6  
W

Latitude: 40.376693 Longitude: -105.056970

### CORRECTIVE ACTIONS:

1 CA# 188682

Corrective Action: Fencing is not in compliance. The operator is to maintain best management practices to control and contain all spills/releases of E&P waste to protect the environment, public health, safety and welfare and the environment as required by rule 913.b(5)B.i which requires that Operators will fence or cover open remediation excavations to prevent access when sites are not attended.

Date: 12/07/2023

Response: CA COMPLETED

Date of Completion: 01/22/2024

Per Rule 913.b(5)B.i. the fence around the remediation excavation has been rebuilt to prevent access to site when not attended. See attached photo.

Operator  
Comment:

COGCC Decision: **Not Approved**

COGCC  
Representative: The wrong photolog is attached.

2 ☒ CA# 188683

Corrective Action: Comply with Rule 606.

Date: 12/07/2023

Response: CA COMPLETED

Date of Completion: 01/29/2024

Operator  
Comment: Per Rule 606, weeds around the excavation site have been removed.

COGCC Decision: **Not Approved**

COGCC  
Representative: The wrong photolog is attached.

3 ☒ CA# 188684

Corrective Action: Install sign to comply with Rule 605.

Date: 12/30/2023

Response: CA COMPLETED

Date of Completion: 12/30/2023

Operator  
Comment: Rule 605 does not require signs to be located at excavation projects. A sign is located at the wellhead excavation site, as per 605.a

COGCC Decision: **Not Approved**

COGCC  
Representative: The wrong photolog is attached.

4 ☒ CA# 188685

Corrective Action: In accordance with 913.d.(1) Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered.

Date: 11/30/2023

Response: CA COMPLETED

Date of Completion: 11/30/2023

Operator  
Comment: Under remedial project #17428, investigation is still on-going. Latest Form 27 Doc#403608088 (approved 1/16/24).

COGCC Decision: Approved

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amber Barnett

Signed:

Title: Compliance Specialist

Date: 2/5/2024 12:02:55 PM

## ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u>       |
|------------------------|--------------------------|
| 403669871              | FIR RESOLUTION SUBMITTED |
| 403672174              | Signage and fencing      |

Total Attach: 2 Files