

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/05/2024

Submitted Date:

02/05/2024

Document Number:

713600693**FIELD INSPECTION FORM**Loc ID 334111 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, Evergreen		cogcc.evergreen@enrllc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
334111	LOCATION	AC			-	LOEWS-632S67W 32NENE	RI

**General Comment:**

This is a location and stormwater management inspection.  
See attached photos and additional details within this report.

Location					
Overall Good: <input type="checkbox"/>					
Signs/Marker:					
Type	WELLHEAD				
Comment:	The name on the sign has peeled off.				
Corrective Action:	Install sign to comply with Rule 605.d.			Date:	04/05/2024
Emergency Contact Number:					
Comment:				Date:	
Corrective Action:					
Good Housekeeping:					
Type					
Comment:					
Corrective Action:				Date:	
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Venting:					
Yes/No					
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment:		There is vehicle rutting along the road that will need to be repaired and stabilized with BMPs.				Date: 02/07/2024
Corrective Action:		Install or repair required BMPs per Rule 1002.f.(2)C				
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403677508	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6419551">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6419551</a>
713600694	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6419534">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6419534</a>