

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/30/2024

Submitted Date:

02/06/2024

Document Number:

710500166

FIELD INSPECTION FORM

Loc ID 321098 Inspector Name: Sanchez, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10330
 Name of Operator: INVESTMENT EQUIPMENT LLC
 Address: 558 CASTLE PINES PKWY UNIT B-4
 City: CASTLE PINES State: CO Zip: 80108

Findings:

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------------|-------|-------------------------------|---------|
| Costa, Ryan | | ryan.costa@state.co.us | |
| Bongers, Brent | | bbongers@impetroresources.com | |
| Highberger, Kathryn | | kathrynhighberger@gmail.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------------------|--------|-------------|------------|-----------|------------------------------------|-------------|
| 206034 | WELL | PA | 11/19/2020 | OW | 009-06450 | TANNER SEC REC UNIT 501 | EG |
| 485834 | SPILL OR RELEASE | AC | 01/23/2024 | | - | TANNER SEC REC UNIT-635S46W/11NENE | EI |

General Comment:

[This is a follow-up Environmental Inspection for the Tanner "E" 1 P&A well location API # 05-009-06450 Located in Baca County Colorado.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|---|-------|--|
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unused equipment is still present on location | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Impacted soils remain on the location | | |
| Corrective Action: | | Date: | |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 206034 Type: WELL API Number: 009-06450 Status: PA Insp. Status: EG

Facility ID: 485834 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: OIL Estimated Spill Volume: _____

Comment: Areas of impacts are still present on the location and soil piles remain. Additionally, the Impacts to native soils adjacent to the location are still present. Operator has filed a Form 19 for the site investigation and cleanup of affected soils. Spill ID # 485834

Corrective Action: Pursuant to Rule 912.b.(6) Operator is required to submit a Form 19 Supplemental Report for the associated spill within 90 days of the spill date requesting closure pursuant to Rule 913.h and supported by adequate documentation to demonstrate that the Spill or Release has been fully cleaned up and complies with Table 915-1; or A Form 27 if any of the criteria listed in Rules 912.b.(6).B.i-iii apply. If Remediation will continue under an approved Form 27, the Operator will also submit a Form 19 – Supplemental which requests closure of the Spill or Release and includes the Remediation project number assigned by the Director. Form 19 Supplemental is due by April 7, 2024. Date: 04/07/2024

Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Waste Management:

| Type | Management | Condition | GPS (Lat) | (Long) |
|-------------------|---|------------|-----------|-------------|
| Oily Soil | Piles | Inadequate | | |
| Comment | Stockpiles of soil are still present on the location. At the time of inspection, it was observed some larger dirt clods impacted by oily material were removed. | | | |
| Corrective Action | | | | Date: _____ |

Spill/Remediation:

Comment: _____
 Corrective Action: _____ Date: _____

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

COGCC Comments

| Comment | User | Date |
|---|-----------|------------|
| Stockpiles of soil are still present on the location | sanchezcc | 02/06/2024 |
| Operator has filed a Form 19 for the site investigation and cleanup of affected soils. Spill ID # 48583 | sanchezcc | 02/06/2024 |
| Unused equipment is still present on location Comply with 1004 Rules. | sanchezcc | 02/06/2024 |
| Impacted soils remain on the location Cleanup soils and manage per Rule 905 | sanchezcc | 02/06/2024 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------|---|
| 403678881 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6420782 |
| 710500167 | Location Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6420772 |