

Inspection Photos

Loc: 309618

Operator: KTM OPERATING LLC

Inspection Date: 2/13/2024

County: LINCOLN



Inspection Photos




Photo 1. Facing west along the access road. Vehicles have widened the road at this area causing unnecessary disturbance to to lack of maintenance of the road. The road will need to be repaired and disturbance must be reclaimed..



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:309618 | Date: 2/13/2024

Inspection Photos



February 13, 2024
+38.861674,-103.568809

Photo 2. Facing southwest toward the onsite tank battery and vertical treaters.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:309618 | Date: 2/13/2024

Inspection Photos



Photo 3. Facing toward the backside of the treater. There has been oil leaked out onto the ground that must be cleaned up.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:309618 | Date: 2/13/2024

Inspection Photos



Photo 4. There are oil saturated soils around the treater that us be cleaned up.



Inspection Photos



Photo 5. There is oil puddled up where the hoses go into the shed which indicates saturated soils and unknown amount of spill volume.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:309618 | Date: 2/13/2024

Inspection Photos



Photo 6. Inside the shed next to the treater. There is oil saturated soils inside the shed. There are full buckets of oil that appear to be collecting oil from leaking pipes.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:309618 | Date: 2/13/2024

Inspection Photos



Photo 7. Facing toward the tank battery at the southwest side. There is some weed debris inside the containment that needs to be removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:309618 | Date: 2/13/2024

Inspection Photos



Photo 8. There is an oil filled milk jug that has tipped over and leaked oil onto the ground.



Photo 9. There is oily soils around the wellhead that need to be cleaned up.

