

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/07/2024

Submitted Date:

02/13/2024

Document Number:

693701104

FIELD INSPECTION FORM

Loc ID 331861 Inspector Name: ALLISON, RICK On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
General, All inspections	(970) 332-3520	cogccinspection@pdce.com	All PDC inspection
Remediation-Spill, PDC		COGCCSpillRemediation@pdce.com	
Waggoner, Kyle		kyle.waggoner@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267066	WELL	PA	04/06/2020	OW	123-21411	BOOTH 44-35	EI

General Comment:

[ECMC Environmental Inspection related to Remediation Project 15357.](#)

Inspected Facilities

Facility ID: 267066 Type: WELL API Number: 123-21411 Status: PA Insp. Status: EI

Environmental

Spill/Remediation:

Comment: Operator submitted Form 27 Doc# 402354435, Remediation Project 15357 for abandonment of a buried produced water vessel associated with the Booth 44-35 API 05-123-21411. It appears Operator provided incorrect lat/lon for this remediation project, and provided incorrect site maps for soil sampling beneath produced water vessel. Operator's lat/lon plots at the Noble Energy Karleberg State 36-45 (API 05-123-26394) on County Road 74. See Field Inspection Report 693701109.

See also Remediation Project 24998 for Spill 482092.

Documentation included in Field Inspection Report 679602138 and aerial imagery documents produced facilities were located at latitude 40.52409 longitude -104.6208.

Remediation Project 15357 will be unresolved.

Corrective Action:	<p style="color: red;">Submit a Form 27 Supplemental for Remediation Project 15357 that includes the correct lat/lon for the former production facilities, and a plan for investigation of potential impacts at production facility. Include a root cause to address the incorrect reporting of the remediation investigation.</p>	Date: <u>03/08/2024</u>
--------------------	--	-------------------------

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403685644	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6427806