

State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403696936

Date Received:
02/23/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 7800
Name of Operator: BEREN CORPORATION
Address: 2020 N BRAMBLEWOOD STREET
City: WICHITA State: KS Zip: 67206

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Kay, Michael</u>	<u>316-249-7597</u>	<u>kaym@berexco.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 711900205
Inspection Date: 01/26/2024 FIR Submit Date: 01/26/2024 FIR Status: _____

Inspected Operator Information:

Company Name: BEREN CORPORATION Company Number: 7800
Address: 2020 N BRAMBLEWOOD STREET
City: WICHITA State: KS Zip: 67206

LOCATION - Location ID: 312144

Location Name: BREWER 'A'-68N53W Number: 15SESE County: LOGAN
Qtrqtr: SESE Sec: 15 Twp: 8N Range: 53W Meridian: 6
Latitude: 40.655980 Longitude: -103.280983

FACILITY - API Number: 05-075- -00 Facility ID: 218987

Facility Name: BREWER 'A' Number: 3
Qtrqtr: SESE Sec: 15 Twp: 8N Range: 53W Meridian: 6
Latitude: 40.655980 Longitude: -103.280983

CORRECTIVE ACTIONS:

1 CA# 191386

Corrective Action: REPAIR LEAK AT GEARBOX PER RULE 608e Date: 02/10/2024

Response: CA COMPLETED Date of Completion: 02/15/2024

Operator Comment: Leak at Gearbox has been repaired, photos of pumping unit after repair work are attached as Figure 1 and Figure 2.

COGCC Decision: _____

COGCC
Representative:

2 CA# 191387

Corrective Action: FILL RUTS AND GRADE LEASE ROAD - REPAIR AND MAINTAIN LEASE ROAD
PER RULE 204 - SEE ATTACHED PHOTOGRAPHS

Date: 02/26/2024

Response: CA COMPLETED

Date of Completion: 02/20/2024

Operator
Comment:

Lease road repaired and graded. Photos of lease road are attached as Figure 3 and Figure 4.

COGCC Decision:

COGCC
Representative:

3 CA# 191388

Corrective Action: REPAIR LEAK PJ GEARBOX - REMOVE AND REMEDIATE EFFECTED SOILS

Date: 02/10/2024

Response: CA COMPLETED

Date of Completion: 02/15/2024

Operator
Comment:

Gearbox leak has been repaired. Roustabouts cleaned up location. Photos of wellsite after cleanup was completed are attached as Figure 5 and Figure 6.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Cleanup was done as soon as possible given the schedules of roustabouts used to do the cleanup work.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Kay

Signed:

Title: Division Engineer

Date: 2/23/2024 12:59:29 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403696959	Evidence leak on gearbox was repaired.
403696960	Evidence leak on gearbox was repaired.
403696973	Photo of repaired lease road at wellsite looking South.
403696975	Photo of repaired lease road looking North.
403696978	Photo of cleaned up well location.
403696980	Photo of cleaned up well location.

Total Attach: 6 Files