

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC EXXON W43-28 Pad
Location ID: 335229



**Location Overview: Location is within High
Priority/Density/NSO/Black Bear Habitat areas. Location is
approximately 18 yards from a creek/drainage that
contributes to the Colorado River.
Section/Township/Range: 28 6S95W**



Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC EXXON W43-28 Pad
Location ID: 335229



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.



Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC EXXON W43-28 Pad
Location ID: 335229



Photo # 7108 Sediment trap needs maintenance



Photo # 7109 Sediment trap needs maintenance

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC EXXON W43-28 Pad
Location ID: 335229



Photo # 7110 Sediment trap needs maintenance



Photo # 7111 Check dam & berm need maintenance