

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/16/2024

Submitted Date:

02/20/2024

Document Number:

713600755

FIELD INSPECTION FORM

Loc ID 333421 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10705
 Name of Operator: EVERGREEN NATURAL RESOURCES LLC
 Address: 1875 LAWRENCE ST STE 1150
 City: DENVER State: CO Zip: 80202

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, Evergreen		cogcc.evergreen@enrllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
333421	LOCATION	AC			-	SOUTHPAW-631S66W 36NWSE	RI

General Comment:

[This is a location and stormwater management inspection of the SOUTHPAW #33-36 wellsite. See attached photos and additional details within this report.](#)

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:			
Type			
Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is a culvert filled in with sediment at the road intersection near the wellsite. Stormwater is going across and eroding the road at this area.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 02/22/2024

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403692749	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6435590
713600756	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6435586