

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403694147

Date Received:

03/01/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Toews, Wesley

wtoews@blm.gov

TEP

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 708902781

Inspection Date: 01/10/2024

FIR Submit Date: 01/14/2024

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335271

Location Name: FEDERAL-66S94W Number: 17SWSE County: _____

Qtrqtr: SWSE Sec: 17 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.520229 Longitude: -107.908801

FACILITY - API Number: 05-045-00 Facility ID: 335271

Facility Name: FEDERAL-66S94W Number: 17SWSE

Qtrqtr: SWSE Sec: 17 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.520229 Longitude: -107.908801

CORRECTIVE ACTIONS:

1 ☒ CA# 190060

Corrective Action: Operators will prevent & minimize adverse impacts to wildlife resources.

Date: 01/21/2024

Response: CA COMPLETED

Date of Completion: 01/19/2024

Operator Comment: Hole on the southern slope near a sediment trap identified as a wildlife hazard has been addressed. Corrective Action complete.

COGCC Decision: Approved pending re-inspection

COGCC Representative:		
2	<input checked="" type="checkbox"/> CA# 190061	
Corrective Action:	Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved.	Date: 01/29/2024
Response:	CA COMPLETED	Date of Completion: 01/19/2024
Operator Comment:	Roadside ditch at the pad entrance has been bladed/graded to address downcutting. Corrective Action complete	
COGCC Decision:	Approved pending re-inspection	
COGCC Representative:		

<u>OPERATOR COMMENT AND SUBMITTAL</u>	
Comment:	CA #190060: Hole on the southern slope near a sediment trap identified as a wildlife hazard has been fixed. Corrective Action complete. CA #190061: Roadside ditch at the pad entrance has been bladed/graded to address downcutting. Corrective Action complete
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: Jordan Veith	Signed: _____
Title: TEP Representative	Date: 3/1/2024 12:08:06 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403694147	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files