

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403694614

Date Received:

03/01/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Trujillo, Aaron

aaron.trujillo@state.co.us

TEP

COGCCInspectionReports@terraep.com

Toews, Wesley

wtoews@blm.gov

COGCC INSPECTION SUMMARY:

FIR Document Number: 708902678

Inspection Date: 01/02/2024

FIR Submit Date: 01/02/2024

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 324076

Location Name: FEDERAL-66S94W Number: 17SESW County: _____

Qtrqr: SESW Sec: 17 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.519099 Longitude: -107.913831

FACILITY - API Number: 05-045- -00 Facility ID: 324076

Facility Name: FEDERAL-66S94W Number: 17SESW

Qtrqr: SESW Sec: 17 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.519099 Longitude: -107.913831

CORRECTIVE ACTIONS:

1 ☒ CA# 189763

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved.

Date: 01/17/2024

Response: CA COMPLETED

Date of Completion: 01/15/2024

Culvert at pad entrance has been cleaned out. The rip rap runs have been repaired and maintained. Berm on the

Operator: north side of the pad has been repaired. Control measures along the lease road have been maintained.
Comment: Corrective Action complete.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Culvert at pad entrance has been cleaned out. The rip rap runs have been repaired and maintained. Berm on the north side of the pad has been repaired. Control measures along the lease road have been maintained. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: _____

Title: TEP Representative

Date: 3/1/2024 1:21:30 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403694614	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files