

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/05/2024

Submitted Date:

03/06/2024

Document Number:

702502437

FIELD INSPECTION FORM

Loc ID 316207	Inspector Name: Burchett, Kirby	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 12 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE
Operator Information: OGCC Operator Number: 10775 Name of Operator: KT RESOURCES LLC Address: 3381 WESTBROOK LANE City: HIGHLANDS State: CO Zip: 80129				

Contact Information:

Contact Name	Phone	Email	Comment
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
Baumgras, Dan	(307) 321-3299	Dan@KT-Res.com	
Adams, Karen	(303) 886-8733	adams@kt-res.com	
Gale, Tony	(303) 886-8733	tony@kt-res.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257080	WELL	SI	11/01/2023	GW	103-10006	WRD UNIT 29-21	SI

General Comment:**ECMC Inspection Report Summary**

On Tuesday, 03/05/2024, Inspector Kirby Burchett, conducted a follow up field inspection at KT Resources LLC on the WRD Unit 29-21 well, Location #316207, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District, Black Bear area with High Priority, NSO, Density and Other Consultation Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Insp. #707800290 on 4/11/23 by Inspector Scott Ramsey. The following Corrective Actions were issued and original due dates will remain on any unresolved CA's:

1. No BMP's installed to prevent sediment migration from occurring on location. (Unresolved)
2. No API posted on well head or battery signage. (Resolved)
3. Chemical and oil tank containment full of fluid not sufficient to contain possible spill. (Resolved)
4. Chemical tank label is illegible. (Resolved)
5. Meter calibration card not conspicuously posted. (Resolved)

Refer to Inspection Photos for observed compliance issues.

While there during normal operations the following compliance issue was observed:

1. Gas meter calibration out of date

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	As Location Entrance signs are replaced: The Well name; The Commission's Location identification number (ID #); The Operator's telephone number where it may be reached at all times; and the Telephone number(s) for local emergency services (911 where available) will be required.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	As Wellhead signs are replaced: The Well name; The API Number; and Its legal location, including the quarter/quarter section will be required.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Operators will ensure that container and tank labels are well maintained and legible, and will replace damaged or vandalized labels within 10 days of discovery that the label is no longer legible or is damaged.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: (800) 288-0560 or 911

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	Pipe rail and barbed wire		
Corrective Action:		Date:	

Equipment:

Type: Deadman # & Marked	# 4		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			

Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration out of compliance.		
Corrective Action:	Meters will be calibrated annually unless more frequent calibration is required by contractual obligations or by the Director.	Date:	03/16/2024
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks on containments		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:	Unlined			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:	Unlined			
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	257080	Type:	WELL	API Number:	103-10006	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <div>Last Production - October 2023 December 2023 Production Report</div>									
Corrective Action: _____ Date: _____									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
		Ditches				
				Material Handling And Spill Prevention		

Comment: 1. Some areas of location show signs of lack of stabilization which in turn can lead to tracking issues.
 2. Access road shows signs of lack of stabilization
 3. No BMP's installed to prevent sediment migration from occurring on location.

Corrective Action: **Install or repair required BMPs**

Date: 05/23/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702502438	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6456324