

RECEIVED  
DEC 6 1972

OFFICE OF THE STATE COMMISSIONER

A. T. SKAER - MILLARD HUEY

Lee-Lusby #1  
NW/NE Sec. 2, T2N, R57W  
Morgan County, Colorado

Washdown

KB - 7' above GL

- 11-4-72 Ran 7 7/8" bit - drilled cement 120' to 188'.  
Pulled bit - ran 2 3/8" tubing to 600'. Hit bridge.
- 11-5-72 Circulated bridge out of hole.  
Ran tubing to 5540' - 180 joints.  
Pulled tubing after circulating.  
Ran 7 7/8" bit - ran 30 stands..
- 11-6-72 Ran bit to 5540'  
Tight at top of Niobrara and at Bentonite. Rotated thru.  
Circulated hole - Pulled tubing , pulled 73 joints. Joint  
had pulled out of collar.  
In hole 106 joints of tubing and drill collar with 7 7/8" bit.  
Ran overshot. Fish is up hole. Bit in Bentonite.  
Caught fish - would pull off with 16,000# pull.  
Pulled tubing and overshot.
- 11-7-72 Ran overshot - would pull off fish. Fish fell to bottom.  
Unable to get over fish.  
Pulled overshot.  
Ran with dog legged joint. Unable to get down to fish.  
Pulled tubing and overshot.
- 11-8-72 Ran 7 5/8" wall hook on bottom of overshot.  
Lacked 240' getting to fish. Pulled tubing. Ran overshot with  
7" skirt. Unable to catch fish.  
Pulled tubing. Ran 7 7/8" bit. Went to 1612' - reamed 60'.
- 11-9-72 Running 7 7/8" bit and reaming hole - Reamed to top of fish, 2312'.  
Pulled bit and ran 7 5/8" wall hook below overshot.  
Were able to hook tubing but unable to work overshot over top  
of tubing so fish could be caught.
- 11-10-72 Attempted to get over fish with overshot - unsuccessful.  
Layed down tubing and fishing tool.  
Plugged hole with 15 sacks of cement in bottom of surface pipe.  
120' to 168' and 10 sacks in top 2' below ground level to 42'.  
Due to washed out condition of hole, were unable to get fish centered  
so that overshot would go over fish.  
Recommended plugging and abandoning.

  
Carl A. Houy