

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/05/2024

Submitted Date:

03/05/2024

Document Number:

713300657

FIELD INSPECTION FORM

 Loc ID 320238 Inspector Name: Kester, Michael On-Site Inspection 2A Doc Num: _____
Operator Information:OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments1 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|-------------------|--------------|------------------------------|---------------------------------|
| , KPK | 303-825-4822 | cogcc@kpk.com | all inspections |
| Kirschner, Steven | | steven.kirschner@state.co.us | |
| Silver, Randy | 720-827-6688 | randy.silver@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 203184 | WELL | SI | 05/01/2021 | OW | 001-08693 | WEIGANDT, JOHN H. A 1 | SI |

General Comment:

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|-------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | good, Faded | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|---------------|-------|--|
| Type | PUMP JACK | | |
| Comment: | safety guards | | |
| Corrective Action: | | Date: | |

Equipment:

| Type | Area | Volume | corrective date |
|---------------------------|------------------------------|--------|-----------------|
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 2 | | |
| Comment: | electrical disconnect panels | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: | electric motor | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | piped to surface | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|----------|--|--|
| Type | | |
| Comment: | | |

Corrective Action:

Date:

Inspected Facilities

Facility ID: 203184 Type: WELL API Number: 001-08693 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: FLOWLINE AVAILABLE-CONNECTED

Comment: Well was found in state of Temporary Abandonment.
Well is overdue for Mechanical Integrity Test (MIT) MIT require 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well.
Well can only be returned to SI status if it has produced (without mechanic intervention) within 2 years per Rule 319.b.
Valves appeared to be closed at time of inspection

Corrective Action: Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 417 and 210. **Date:** 04/08/2024

BradenHead

Date of Last Brhd Test: 07/03/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ **Date:** _____

COGCC Comments

| Comment | User | Date |
|--|---------|------------|
| <p>ECMC Inspection Report Summary Inspector Michael Kester, conducted an on-site inspection. Location: Weigandt John H A 1 Operator: KPK API#: 123-08693 County: Weld While there, I observed well site with pumping unit During this inspection, the following possible compliance issues were observed: Mechanical integrity Testing Temporarily Abandoned Wells, Rule417c, corrective action date 4-8-2024</p> <p>Weather conditions: over cast and dry A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.</p> <p>This inspection does not nullify any orders or NOAV from the ECMC This is a continuing education inspection</p> | kesterm | 03/05/2024 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 713300658 | site pic | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6458970 |