

# Inspection Photos

3/06/2024

**Operator:** TEP ROCKY MOUNTAIN LLC #96850

**Location ID:** 324180

**Inspection Doc:** 696205663

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 324180



**Photo 1:** Photos 1-2 taken from the working pad surface of the Location. Photos examples showing work to stabilize the working pad surface, as well as to minimize tracking and sediment transport is insufficient. Operator appears to have only placed gravel material over select portions of the Location. BMP alone is inadequate as tracking and degradation issues are recurring; sediment has already filled in large areas of the pad that had been graveled.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 324180



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 324180



**Photo 3:** Photos taken from the west end of the Location. Photo shows stormwater and erosion control BMPs to manage runoff and minimize erosion, degradation and sediment transport remain missing or insufficient.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources