

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/28/2024

Submitted Date:

03/07/2024

Document Number:

708200961

FIELD INSPECTION FORM

Loc ID 439416 Inspector Name: Edwardson, Dylan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 8960
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 10 Number of Comments
- 7 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		inspections@civiresources.com	All Inspections
,		EHSRC@bonanzacrk.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
439416	LOCATION	AC			-	Pronghorn 24-7 Booster Station	RI
482105	GAS COMPRESSOR STATION	AC	04/01/2022		-	Pronghorn 24-7 Booster Station	RI

General Comment:

[This is an Interim Reclamation and Stormwater Inspection for Location ID \(439416\).](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Cigarette butt observed on location. Refer to attached inspection photos.		
Corrective Action:	Implement actions to fully comply with Rule 610 regarding fire prevention and protection.	Date:	03/14/2024
Type	TRASH		
Comment:	Trash and debris was observed throughout the location. Refer to attached inspection photos for documentation.		
Corrective Action:	Comply with Rule 606 and remove all trash and debris from location.	Date:	03/14/2024
Type	WEEDS		
Comment:	Tumbleweed accumulations were observed throughout the location and within production equipment. Refer to attached inspection photos for documentation.		
Corrective Action:	Comply with Rule 606 and remove all tumbleweed accumulations from location and production equipment.	Date:	03/14/2024
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment observed on the eastern side of the location. Refer to attached inspection photos for documentation.		
Corrective Action:	Comply with Rule 606 and remove any unused equipment.	Date:	03/14/2024

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Other	#		corrective date
Comment:	Stained soils (e.g. drips and drabs) observed at flare unit, compressors and storage tanks at compressors. Free fluid (e.g. antifreeze) observed within secondary containment units at compressor. Bull plugs weeping at tank battery. Refer to attached inspection photos for documentation.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).D.		Date: 03/14/2024

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 439416 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Facility ID: 482105 Type: GAS API Number: - Status: AC Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? Fail
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Fail
 Production areas have been stabilized? Fail Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation Fail

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment This location does not comply with Rule 1003. During this inspection, it was observed that interim areas are not progressing towards Rule 1003 standards and regulations. Evidence of bare/exposed soils and and undesirable vegetation was observed throughout. Soils appear to be unstabilized with evidence of wind erosion and animal burrows throughout. Additional reclamation activities are required to comply with Rule 1003. Refer to attached inspection photos for documentation.

Corrective Action Perform reclamation in accordance to Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until the location meets Rule 1003 standards.

Date 04/30/2024

Overall Interim Reclamation Fail

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation _____

Well Release on Active Location

Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: This location does not comply with Rule 1002.f. During this inspection, it was observed that portions of the production areas were experiencing erosion degradation. Maintenance/repairs of unstabilized soils and/or implementation of stormwater control measures is required to manage stormwater runoff and runoff at this location. Refer to attached inspection photos for documentation.

Corrective Action: Install or repair required BMPs in accordance with good engineering practices per Rule 1002.f.

Date: 03/14/2024

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708200975	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6459213