

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403694977

Date Received:  
03/01/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>TEP</u>		<u>COGCCInspectionReports@terraep.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 708301421  
Inspection Date: 12/18/2023 FIR Submit Date: 12/21/2023 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335316

Location Name: PA-66S95W Number: 33NESW County: \_\_\_\_\_  
Qtrqr: NESW Sec: 33 Twp: 6S Range: 95W Meridian: 6  
Latitude: 39.479489 Longitude: -108.007323

FACILITY - API Number: 05-045-00 Facility ID: 335316

Facility Name: PA-66S95W Number: 33NESW  
Qtrqr: NESW Sec: 33 Twp: 6S Range: 95W Meridian: 6  
Latitude: 39.479489 Longitude: -108.007323

CORRECTIVE ACTIONS:

1  CA# 189470

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to comply with Rule 1002. Date: 01/05/2024

Response: CA COMPLETED Date of Completion: 01/17/2024

Operator Comment: Location and access road has been bladed/graded to remove rutting. Rills south of the separators/tank battery have been repaired. Corrective Action complete.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Location and access road has been bladed/graded to remove rutting. Rills south of the separators/tank battery have been repaired. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: \_\_\_\_\_

Title: TEP Representative

Date: 3/1/2024 1:45:45 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

403694977	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files