

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403714413

Date Received:

03/11/2024

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Romana Cowden

Phone

720-951-5895

Email

COGCC.inspections@caerusoilandgas.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 701103931

Inspection Date: 02/23/2024

FIR Submit Date: 03/01/2024

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 467272

Location Name: ELU J14 Number: FED-496 PAD County: \_\_\_\_\_

Qtrqtr: NESW Sec: 14 Twp: 4S Range: 96W Meridian: 6

Latitude: 39.700947 Longitude: -108.137218

### FACILITY - API Number: 05-103-00 Facility ID: 467272

Facility Name: ELU J14 Number: FED-496 PAD

Qtrqtr: NESW Sec: 14 Twp: 4S Range: 96W Meridian: 6

Latitude: 39.700947 Longitude: -108.137218

### CORRECTIVE ACTIONS:

1 CA# 192592

Corrective Action:

Date: 03/08/2024

Form 19 (SUPPLEMENTAL) doc # 403690289 has no Root Cause and repair made to prevent reoccurrence.  
No coordination with ECMC Western Integrity Inspector, Mike Longworth, regarding pipeline excavation, assessment, and repair.  
No notice provide a minimum 48-hours of advance notice to Mike Longworth via email (michael.longworth@state.co.us) prior to pressure testing of equipment.  
Submit In the Supplemental Form 19, identify the root cause of the failure and explain how reoccurrence on this pipeline and the other pipelines associated with this facility will be prevented, per Rule 912.d.(3).  
Respond to why no coordination and no notice to test equipment was provided by FIRR (Field Inspection Report Resolution)

Response: CA COMPLETED

Date of Completion: 03/06/2024

Operator  
Comment:

There was confusion about the reporting requirements for Return to Service. Caerus communicated with Mike Longworth on 3/4/2024 and 3/06/2024 via phone to provide an update on the current status of the J14 496 pipeline and process for future repairs and notifications. The root cause of the J14 failure was discussed on the phone call and additional information will be provided in a supplemental form 19.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

--

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

--

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed: \_\_\_\_\_

Title: EHS

Date: 3/11/2024 9:49:49 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
-----------------	-------------

--	--

Total Attach: 0 Files