

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SILT VALLEY 34C-22-692 Pad
Location ID: 335438



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas.**
Section/Township/Range: 22 6S92W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SILT VALLEY 34C-22-692 Pad
Location ID: 335438



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SILT VALLEY 34C-22-692 Pad
Location ID: 335438



Photo # 9284 Chemical tank containment approximately 7/8th full of fluid/failure to maintain chemical BMP/BMP insufficient to contain possible spill



Photo # 9285 Rip Rap run on sediment trap outlet needs maintenance (N/NE area of location)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SILT VALLEY 34C-22-692 Pad
Location ID: 335438



**Photo # 9286 Erosion & transport of sediment off
location/insufficient BMP's/runoff controls**