

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC STRANAHAN 41C-27 Pad
Location ID: 335437



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas & in close proximity
to NSO Habitat area.**

Section/Township/Range: 27 6S92W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources


Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC STRANAHAN 41C-27 Pad
Location ID: 335437



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC STRANAHAN 41C-27 Pad
Location ID: 335437



Photo # 9692 Chemical tank containment full of fluid/Failure to maintain chemical BMP/BMP insufficient to contain possible spill.




Photo # 9693 Chemical tank containment full of fluid/Failure to maintain chemical BMP/BMP insufficient to contain possible spill.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC STRANAHAN 41C-27 Pad
Location ID: 335437



Photo # 9694 Chemical tank & containment are also unused equipment