

Operator: Bonanza Creek Energy
Location Name: Pronghorn 24-7 Booster Station
Loc ID: 439416
Inspection: 708200961



Exhibit A



Exhibit B



Exhibit C



Exhibit D



Exhibit E



Exhibit F



Exhibit G



Exhibit H



Exhibit I



Exhibit J



Exhibit K



Exhibit L



Exhibit M



Exhibit N



Exhibit O

CA: Cigarette butt observed on location. Implement actions to fully comply with Rule 610 regarding fire prevention and protection.

CA Resolution: Cigarette butt has been removed and actions have been implemented to comply with Rule 610.

CA: Trash and debris were observed throughout the location. Comply with Rule 606 and remove all trash and debris from location.

CA Resolution: Trash and debris has been removed to comply with Rule 606.

CA: Tumbleweed accumulations were observed throughout the location and within production equipment. Comply with Rule and remove all tumbleweed accumulations from location and production equipment.

CA Resolution: Tumbleweeds have been removed from the location.

CA: Unused equipment observed on the eastern side of the location. Comply with Rule 606 and remove any unused equipment.

CA Resolution: Unused equipment has been removed to comply with Rule 606.

CA: Stained soils (e.g. drips and drabs) observed at flare unit, compressors and storage tanks at compressors. Free fluid (e.g. antifreeze) observed within secondary containment units at compressor. Bull plugs weeping at tank battery. Conduct maintenance on equipment, cleanup stained material and review self-inspection processes per Rule 1002.f.(2).D.

CA Resolution: Maintenance has been performed on equipment and stains have been cleared to comply with Rule 1002.f.(2).D.

CA: This location does not comply with Rule 1003. During this inspection, it was observed that interim areas are not progressing towards Rule 1003 standards and regulations. Evidence of bare/exposed soils and undesirable vegetation was observed throughout. Soils appear to be un-stabilized with evidence of wind erosion and animal burrows throughout. Additional reclamation activities are required to comply with Rule 1003. Perform reclamation in accordance with Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil and continue to monitor and manage this site until the location meets Rule 1003 standards.

CA Resolution: This location has been reclaimed to comply with Rule 1003.

CA: This location does not comply with Rule 1002.f. During this inspection, it was observed that portions of the production areas were experiencing erosion degradation. Maintenance/repairs of un-stabilized soils and/or implementation of stormwater control measures is required to manage stormwater run-on and runoff at this location. Install or repair required BMPs in accordance with good engineering practices per Rule 1002.f.

CA Resolution: BMPs have been put in place to comply with Rule 1002.f.