

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403720091

Date Received:

03/14/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

0 CA Completed
1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Victoria Dizghinjili	303-825-4822	vdizghinjili@kpk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 702403186

Inspection Date: 03/13/2024

FIR Submit Date: 03/13/2024

FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 336214

Location Name: Nelson-Stromquist Number: 11-21-13H County: WELD

Qtrqtr: NESW Sec: 21 Twp: 2N Range: 68W Meridian: 6

Latitude: 40.122380 Longitude: -105.010600

FACILITY - API Number: 05-123-00 Facility ID: 241393

Facility Name: MILTON H. NELSON Number: 1

Qtrqtr: NESW Sec: 21 Twp: 2N Range: 68W Meridian: 6

Latitude: 40.122380 Longitude: -105.010600

CORRECTIVE ACTIONS:

1 CA# 193012

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 04/13/2024

Response: FACTUAL REVIEW REQUEST

Basis for Review: CA dates are not per the guidelines

Operator Comment: This well does not fit the definition of Temporarily Abandoned as defined in ECMC 100 Series rules. Instead, this well is Shut-in due to the ECMC Director's 901.a Order dated April 12, 2021. It is capable of production without a downhole intervention, removal of a plug, or addition of equipment. KPK disagrees with the requirement to

conduct an MIT on this well and has previously requested a partial withdrawal of the 901.a Order and the ability to unload well liquids thereby resetting the clock for MIT testing. In the alternative, KPK proposed continuously monitor bradenhead pressures to satisfy the MIT requirement; this practice was previously approved and implemented by another operator. KPK renews it request to unload the Shut-in 901.a Order wells.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili

Signed: _____

Title: ET

Date: 3/14/2024 3:31:18 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files