

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403701995

Date Received:
03/15/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>TEP</u>		<u>COGCCInspectionReports@terraep.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 708902418
Inspection Date: 12/04/2023 FIR Submit Date: 12/05/2023 FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 322405

Location Name: CLOUGH-66S94W Number: 15SESE County: _____
Qtrqtr: SESE Sec: 15 Twp: 6S Range: 94W Meridian: 6
Latitude: 39.519969 Longitude: -107.867689

FACILITY - API Number: 05-045-00 Facility ID: 322405

Facility Name: CLOUGH-66S94W Number: 15SESE
Qtrqtr: SESE Sec: 15 Twp: 6S Range: 94W Meridian: 6
Latitude: 39.519969 Longitude: -107.867689

CORRECTIVE ACTIONS:

1 CA# 188916

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved. Date: 12/20/2023

Response: CA COMPLETED Date of Completion: 12/22/2023

Operator Comment: Location and access road has been bladed/graded to repair the road degradation. Location on the road where erosion and down slope degradation occurred has been maintained to prevent further degradation. Corrective Action complete.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

--

OPERATOR COMMENT AND SUBMITTAL

Comment:

Location and access road has been bladed/graded to repair the road degradation. Location on the road where erosion and down slope degradation occurred has been maintained to prevent further degradation. Corrective Action complete.
--

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: _____

Title: TEP Representative

Date: 3/15/2024 3:33:05 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403701995	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files