

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC BBC 12A-24 Pad
Location ID: 335442



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas.**

Section/Township/Range: 23 6S92W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC BBC 12A-24 Pad
Location ID: 335442



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC BBC 12A-24 Pad
Location ID: 335442



Photo # 9197 Tunnel erosion through berm/BMP needs maintenance

Photo # 9198 Tunnel erosion through berm/BMP needs maintenance