

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/15/2024

Submitted Date:

03/18/2024

Document Number:

713600825

**FIELD INSPECTION FORM**

Loc ID 314174 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 74165  
Name of Operator: RENEGADE OIL & GAS COMPANY LLC  
Address: 6155 S MAIN STREET #225  
City: AURORA State: CO Zip: 80016

**Findings:**

- 10 Number of Comments
- 8 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Ingve, Edward	303-680-4725	ed@renegadeoilandgas.com	
ECMC Enforcement		dnr_cogccenforcement@state.co.us	
Sanchez, Chris		chris.sanchez@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
227719	WELL	PR	06/01/2023	GW	099-06045	KERN ESTATE 1	RI

**General Comment:**

This is a follow up of the previous reclamation inspections #690204425, 713600492, #713600763.  
The corrective actions of the previous inspections have not been completed.  
Non-compliance with the Rules will be referred to enforcement.  
See attached photos and additional details within this report.

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	There is no tank labeling of the crude oil tank.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Overall Good:

**Spills:**

Type	Area	Volume		
Crude Oil	WELLHEAD			
Comment:	There is oil that has leaked and sprayed out of the wellhead that needs to be cleaned up. Operator was immediately notified during the previous inspection. Previous corrective action has not been completed.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date:	02/23/2024
Crude Oil	Tank			
Comment:	There was a previous leak observed at the tank that spilled crude oil onto the ground and there was no secondary containment. Operator was immediately notified during the previous inspection. It appears some of the impacted material was scrapped away however there is still oily impacted soils around the tanks. There has been no form 19 submitted to report the spill. Previous corrective action has not been completed.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. Report spill or release of E&P waste or produced fluids Remove free fluids and contact EPS staff per Rule 912.b.		Date:	02/23/2024

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
	2	300 BBLs	STEEL AST		
Comment:	There is a new tank installed at the location with significant modification. All new tanks installed must comply with Rule 603.k.o. which requires impervious liner and secondary containment of steel, or other engineered material. The tanks must be removed for proper installation.				
Corrective Action:				Date:	

**Paint**

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:	There is a new tank installed at the location which is now in use. There is currently no secondary containment. Secondary containment must be installed per Rule 603.o. with steel containment and impervious liner. Previous corrective action was not completed and a spill has since occurred. Corrective action must be completed immediately	
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.	Date: 12/15/2023

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Environmental**

**Waste Management:**

Type	Management	Condition	GPS (Lat) (Long)	
Oily Soil	Piles	Inadequate		
Comment	There is oily impacted soils stored on a tarp with no containment to prevent offsite movement of the contaminated material. E&P Waste are not properly stored, handled, transported, treated, recycled, or disposed per Rule 905.			
Corrective Action	Properly dispose of oily waste in accordance with Rule 905.e			Date: 03/20/2024

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB):

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_ Fail \_\_\_\_\_

Comment The location fence is only up on three sides which is preventing agriculture activities and interim reclamation. Fence will need to be removed or properly installed per landowner request. Previous corrective action was not completed.

Corrective Action Comply with the fencing requirements per the 1002a rules

Date **07/11/2023**

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_ Fail \_\_\_\_\_

Comment Guy line anchors are not marked. Previous corrective action was not completed.

Corrective Action Install proper guy line markers per Rule 1003.a

Date **07/11/2023**

1003b. Area no longer in use? Fail Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? Fail  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established Fail

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment The location has not been reduced in size and unused areas of the location are not reclaimed. All unused areas of the location need to be decompacted by crossripping to at least 18 inches and reclaimed for cropland use. Previous corrective action was not completed

Corrective Action Comply with the 1003 interim reclamation rules.

Date 07/11/2023

Overall Interim Reclamation Fail

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:

Date \_\_\_\_\_

Overall Final Reclamation	Well Release on Active Location <input type="checkbox"/>	Multi-Well Location <input type="checkbox"/>
---------------------------	--	--

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713600826	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6470917">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6470917</a>