

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403723236

Date Received:
03/18/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

0 CA Completed
1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: _____
Phone: () Fax: ()
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Victoria Dizghinjili	303-825-4822	vdizghinjili@kpk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 713300689
Inspection Date: 03/12/2024 FIR Submit Date: 03/12/2024 FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC Company Number: 46290
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 318248

Location Name: UPRR 43 PAN AM G-61N67W Number: 29NENW County: WELD
Qtrqtr: NENW Sec: 29 Twp: 1N Range: 67W Meridian: 6
Latitude: 40.027560 Longitude: -104.916700

FACILITY - API Number: 05-123-00 Facility ID: 240961

Facility Name: UPRR 43 PAN AM G Number: 6
Qtrqtr: NENW Sec: 29 Twp: 1N Range: 67W Meridian: 6
Latitude: 40.027560 Longitude: -104.916700

CORRECTIVE ACTIONS:

1 CA# 192981

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 04/12/2024

Response: FACTUAL REVIEW REQUEST

Basis for Review: CA dates are not per the guidelines

This well does not fit the definition of Temporarily Abandoned as defined in ECMC 100 Series rules. Instead, this well is Shut-in due to the ECMC Director's 901.a Order dated April 12, 2021. It is capable of production without a

Operator Comment:	downhole intervention, removal of a plug, or addition of equipment. KPK disagrees with the requirement to conduct an MIT on this well and has previously requested a partial withdrawal of the 901.a Order and the ability to unload well liquids thereby resetting the clock for MIT testing. In the alternative, KPK proposed continuously monitor bradenhead pressures to satisfy the MIT requirement; this practice was previously approved and implemented by another operator. KPK renews it request to unload the Shut-in 901.a Order wells.
COGCC Decision:	
COGCC Representative:	

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili Signed: _____

Title: ET Date: 3/18/2024 2:52:40 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files