

**Storm Water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC EXXON PA 331-34 Pad**  
**Location ID: 335333**



**Location Overview: Location is within High Priority/Density  
Habitat areas. Location is within close proximity to Rule 411a  
Surface Water External Buffer.**

**Section/Township/Range: 34 6S95W**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC EXXON PA 331-34 Pad**  
**Location ID: 335333**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC EXXON PA 331-34 Pad**  
**Location ID: 335333**



**Photo # 388 Chemical containment approximately  $\frac{3}{4}$  full of fluid/Failure to maintain chemical BMP/BMP insufficient to contain possible spill.**