

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403716943

Date Received:

03/12/2024

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 83130  
Name of Operator: STRACHAN EXPLORATION INC

Address: 992 S 4TH AVE SUITE 100-461

City: BRIGHTON State: CO Zip: 80601

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Reed Shawn

3035626530

shawn@strachanexploration.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 713600144

Inspection Date: 08/24/2023

FIR Submit Date: 08/31/2023

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: STRACHAN EXPLORATION INC

Company Number: 83130

Address: 383 INVERNESS PKWY, STE 360

City: ENGLEWOOD State: CO Zip: 80112

### LOCATION - Location ID: 324831

Location Name: FRAZEE-619S50W Number: 6NWNW County: KIOWA

Qtrqr: NWN Sec: 6 Twp: 19S Range: 50W Meridian: 6  
W

Latitude: 38.438830 Longitude: -103.060030

### FACILITY - API Number: 05-061- -00 Facility ID: 213004

Facility Name: FRAZEE Number: 2-6

Qtrqr: NWN Sec: 6 Twp: 19S Range: 50W Meridian: 6  
W

Latitude: 38.438830 Longitude: -103.060030

### CORRECTIVE ACTIONS:

1 CA# 179813

Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.

Date: 06/29/2023

Response: CA COMPLETED

Date of Completion: 03/04/2024

Operator  
Comment: Berm Expanded

COGCC Decision: Not Approved

COGCC Representative: Most recent inspection #713600781 documents that the corrective action was not completed. The berms were reconstructed with impacted soil from a spill that occurred. The area of the tank where spill occurred will require sampling and additional excavation and removal of impacted soils. A modification of the tank area will require secondary containment to be installed per Rule 603.o.

2 ☒ CA# 179814

Corrective Action: Install or repair wildlife protection equipment.

Date: 08/24/2023

Response: CA COMPLETED

Date of Completion: 07/06/2023

Operator Comment: Netting replaced on tank

COGCC Decision: Approved pending re-inspection

COGCC Representative:

3 ☒ CA# 179815

Corrective Action: Comply with the fencing requirements per the 1002a rules

Date: 06/29/2023

Response: CA COMPLETED

Date of Completion: 03/04/2024

Operator Comment: Fence repaired

COGCC Decision: Not Approved

COGCC Representative: Most recent inspection #713600781 documents that the corrective action was not completed.

4 ☒ CA# 179816

Corrective Action: Install sign to comply with Rule 605.h.

Date: 06/29/2023

Response: CA COMPLETED

Date of Completion: 03/04/2024

Operator Comment: Lay down separators are not in use so no signage required , equipment removed from location.

COGCC Decision: Not Approved

COGCC Representative: Unused equipment will need to be removed.

#### OPERATOR COMMENT AND SUBMITTAL

Comment: All deficiencies addressed

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Shawn Reed

Signed: \_\_\_\_\_

Title: Consultant

Date: 3/12/2024 4:51:43 PM

#### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403716943	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files