

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403724689

Date Received:  
03/19/2024

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

1 of 3 CAs from the FIR responded to on this Form

0 CA Completed  
1 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: <u>46290</u>	Contact Name and Telephone:
Name of Operator: <u>KP KAUFFMAN COMPANY INC</u>	Name: _____
Address: <u>1700 LINCOLN ST STE 4550</u>	Phone: (    )                      Fax: (    )
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80203</u>	Email: _____

#### Additional Operator Contact:

Contact Name	Phone	Email
<u>Victoria Dizghinjili</u>	<u>303-825-4822</u>	<u>vdizghinjili@kpk.com</u>

### COGCC INSPECTION SUMMARY:

FIR Document Number: 702403182  
Inspection Date: 03/05/2024                      FIR Submit Date: 03/13/2024                      FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC                      Company Number: 46290  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER                      State: CO                      Zip: 80203

#### LOCATION - Location ID: 333156

Location Name: JILLSON 'A'-62N68W                      Number: 21SWSE                      County: WELD  
Qtrqtr: SWSE                      Sec: 21                      Twp: 2N                      Range: 68W                      Meridian: 6  
Latitude: 40.118760                      Longitude: -105.005970

#### FACILITY - API Number: 05-123- -00                      Facility ID: 240989

Facility Name: JILLSON 'A'                      Number: 1  
Qtrqtr: SWSE                      Sec: 21                      Twp: 2N                      Range: 68W                      Meridian: 6  
Latitude: 40.118760                      Longitude: -105.005970

### CORRECTIVE ACTIONS:

**3** CA# 193009

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 04/13/2024

Response: FACTUAL REVIEW REQUEST

Basis for Review: CA dates are not per the guidelines

Operator Comment: This well does not fit the definition of Temporarily Abandoned as defined in ECMC 100 Series rules. Instead, this well is Shut-in due to the ECMC Director's 901.a Order dated April 12, 2021. It is capable of production without a downhole intervention, removal of a plug, or addition of equipment. KPK disagrees with the requirement to

conduct an MIT on this well and has previously requested a partial withdrawal of the 901.a Order and the ability to unload well liquids thereby resetting the clock for MIT testing. In the alternative, KPK proposed continuously monitor bradenhead pressures to satisfy the MIT requirement; this practice was previously approved and implemented by another operator. KPK renews it request to unload the Shut-in 901.a Order wells.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili

Signed: \_\_\_\_\_

Title: ET

Date: 3/19/2024 12:42:18 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files