

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403719981

Date Received:
03/14/2024

FIR RESOLUTION FORM

Overall Status: BOTH

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

- 1 CA Completed
- 1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290
 Name of Operator: KP KAUFFMAN COMPANY INC
 Address: 1700 LINCOLN ST STE 4550
 City: DENVER State: CO Zip: 80203

Contact Name and Telephone:
 Name: _____
 Phone: () _____ Fax: () _____
 Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Victoria Dizghinjili</u>	<u>303-825-4822</u>	<u>vdizghinjili@kpk.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 713300677
 Inspection Date: 03/12/2024 FIR Submit Date: 03/12/2024 FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC Company Number: 46290
 Address: 1700 LINCOLN ST STE 4550
 City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 317915

Location Name: UPRR 43 PAN AM G-61N67W Number: 29SESE County: WELD
 Qtrqr: SESE Sec: 29 Twp: 1N Range: 67W Meridian: 6
 Latitude: 40.016960 Longitude: -104.907160

FACILITY - API Number: 05-123-00 Facility ID: 240169

Facility Name: UPRR 43 PAN AM G Number: 1
 Qtrqr: SESE Sec: 29 Twp: 1N Range: 67W Meridian: 6
 Latitude: 40.016960 Longitude: -104.907160

CORRECTIVE ACTIONS:

1 CA# 192986

Corrective Action: Comply with Rule 606 Date: 04/12/2024

Response: CA COMPLETED Date of Completion: 03/14/2024

Operator Comment: Pump jack has been delivered to site to be installed. But the installation process was suspended because ECMC Order 901.a. was issued and well is not produced.

COGCC Decision: **Not Approved**

see supervisor comment

COGCC Representative: _____

COGCC Supervisor: 901 order does not affect the completion of installing equipment

2  CA# 192987

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 04/12/2024

Response: FACTUAL REVIEW REQUEST

Basis for Review: CA dates are not per the guidelines

Operator Comment: This well does not fit the definition of Temporarily Abandoned as defined in ECMC 100 Series rules. Instead, this well is Shut-in due to the ECMC Director's 901.a Order dated April 12, 2021. It is capable of production without a downhole intervention, removal of a plug, or addition of equipment. KPK disagrees with the requirement to conduct an MIT on this well and has previously requested a partial withdrawal of the 901.a Order and the ability to unload well liquids thereby resetting the clock for MIT testing. In the alternative, KPK proposed continuously monitor bradenhead pressures to satisfy the MIT requirement; this practice was previously approved and implemented by another operator. KPK renews it request to unload the Shut-in 901.a Order wells.

COGCC Decision: **Not Approved**

COGCC Representative: KPK's request with respect to MIT requirements at wells subject to the Rule 901.a Order was never granted. Therefore, the requirements of Rule 417 and the corrective actions contained in this inspection, remain outstanding.

COGCC Supervisor: KPK's request with respect to MIT requirements at wells subject to the Rule 901.a Order was never granted. Therefore, the requirements of Rule 417 and the corrective actions contained in this inspection, remain outstanding.

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili Signed: _____

Title: ET Date: 3/14/2024 6:33:14 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403719981	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files