

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 531-16 Pad

Location ID: 311629



Photo # 664 From entrance to location



Photo # 665 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 531-16 Pad

Location ID: 311629



Photo # 666 Location

Photo # 667 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 531-16 Pad

Location ID: 311629



Photo # 668 Location



Photo # 669 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 531-16 Pad

Location ID: 311629



Photo # 670 Location



Photo # 671 PRV on separator unit does not comply with CECMC pressure safety device rules & general safety rules.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 531-16 Pad

Location ID: 311629



Photo # 672 PRV on separator unit does not comply with CECMC pressure safety device rules & general safety rules.



Photo # 673 PRV on separator unit does not comply with CECMC pressure safety device rules & general safety rules.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 531-16 Pad

Location ID: 311629



Photo # 674 PRV on separator unit does not comply with CECMC pressure safety device rules & general safety rules.



Photo # 675 PRV on separator unit does not comply with CECMC pressure safety device rules & general safety rules.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 531-16 Pad

Location ID: 311629



Photo # 676 Unmarked deadman



Photo # 677 Same unmarked deadman from a different angle

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 531-16 Pad

Location ID: 311629



Mar 20, 2024 at 12:51:26 PM
CO

Photo # 678 Debris