

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403730345

Date Received:
03/25/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

1 CA Completed
1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Victoria Dizghinjili	303-825-4822	vdizghinjili@kpk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 713300718
Inspection Date: 03/19/2024 FIR Submit Date: 03/19/2024 FIR Status:

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC Company Number: 46290
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 318909

Location Name: SEBOLD, DOROTHY-61N67W Number: 23SESW County: WELD
Qtrqtr: SESW Sec: 23 Twp: 1N Range: 67W Meridian: 6
Latitude: 40.030930 Longitude: -104.860200

FACILITY - API Number: 05-123-00 Facility ID: 242443

Facility Name: SEBOLD, DOROTHY Number: B-2
Qtrqtr: SESW Sec: 23 Twp: 1N Range: 67W Meridian: 6
Latitude: 40.030930 Longitude: -104.860200

CORRECTIVE ACTIONS:

1 CA# 193338

Corrective Action: Comply with Rule 606 Date: 04/19/2024

Response: CA COMPLETED Date of Completion: 03/25/2024

Operator Comment: Dead vegetation around pumping unit & electrical panel areas have been removed. Please see attached pictures.

COGCC Decision:

COGCC
Representative:

2 CA# 193339

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 04/19/2024

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: This well does not fit the definition of Temporarily Abandoned as defined in ECMC 100 Series rules. Instead, this well is Shut-in due to the ECMC Director's 901.a Order dated April 12, 2021. It is capable of production without a downhole intervention, removal of a plug, or addition of equipment. KPK disagrees with the requirement to conduct an MIT on this well and has previously requested a partial withdrawal of the 901.a Order and the ability to unload well liquids thereby resetting the clock for MIT testing. In the alternative, KPK proposed continuously monitor Bradenhead pressures to satisfy the MIT requirement; this practice was previously approved and implemented by another operator. KPK renews it request to unload the Shut-in 901.a Order wells.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili

Signed:

Title: ET

Date: 3/25/2024 3:53:46 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403730538	Weeds removed PIC1
403730540	Weeds removed PIC2

Total Attach: 2 Files