

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/26/2024

Submitted Date:

03/28/2024

Document Number:

713600861

**FIELD INSPECTION FORM**

Loc ID 321653 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96730  
Name of Operator: WILLIFORD ENERGY COMPANY  
Address: 6060 AMERICAN PLAZA SUITE 760  
City: TULSA State: OK Zip: 74135

**Findings:**

- 5 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
GROWNS LARRY		lgrowns@willifordenergy.com	
Sanchez, Chris		chris.sanchez@state.co.us	
Storts, Doug		pds@willifordenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207687	WELL	PR	06/01/2021	OW	017-06622	RHOADES UNIT 5-4	RI

**General Comment:**

This is a location and stormwater management inspection of the RHOADES #5-4 wellsite.  
See attached photos and additional details within this report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	There are areas where vehicle are driving outside of the access road boundary causing unnecessary disturbance that will need to be reclaimed. Repeated or flagrant instance(s) of failure to restrict lease access to lease roads which result in unreasonable land damage or crop losses shall be subject to a penalty under Rule 523.		
Corrective Action:	Operator shall abide by the reclamation rules to minimize surface disturbances per the 1002e rule.	Date:	03/28/2024

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
Lube Oil	Pump Jack		
Comment:	There is oil leaking out of the engine exhaust pipe which is staining the soil and needs to be cleaned up.		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 906. Immediately to stop and clean up 24 hours to remove free fluids. 30-days to remove stained soil.		Date: 03/26/2024
Crude Oil	WELLHEAD		
Comment:	There are signs a spill occurred at the wellsite that spread out west and south of the well with an undetermined amount spilled which will require a spill report and proper clean up. Operator was immediately notified. Emergency number went to voicemail and a message was left regarding this issue.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. Report spill or release of E&P waste or produced fluids Remove free fluids and contact COGCC EPS staff per Rule 912.b. Immediately to stop and clean up, 24 hours to remove free fluids. 24 hours for notification and 72 hours for Initial Form 19 Report.		Date: 03/26/2024

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Fail	Material Handling And Spill Prevention	Fail	

Comment: The cattle guard is filled in with sediment and needs to be cleaned out and maintained. There are areas of access road which are not stabilized or maintained. It appears there are areas where stormwater is pooling and vehicles are driving around the impacted road causing unnecessary disturbance. The access road needs to be repaired and maintained with BMP's such as road base, gravel, culverts, ect. There are also chemical barrels with no secondary containment not properly stored. Corrective action will remian out of compliance until completed.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)

Date: 04/01/2024

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713600862	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6485036">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6485036</a>