

Storm Water Management and Erosion control
Location Name: TEP Rocky Mountain LLC RMV 83-34 Pad
Location # 334888



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas.**

Section/Township/Range: 34 6S94W

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC RMV 83-34 Pad
Location # 334888



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC RMV 83-34 Pad
Location # 334888

Mar 25, 2024 at 10:59:39 AM



Photo # 1197 Lack of stabilization on cut slope