

**Storm Water Management and Erosion control**  
**Location Name: TEP Rocky Mountain LLC Juhan Tank facility**  
**Facility ID # 479723**



**Location Overview: Location is within High Priority/Density/NSO/Black Bear Habitat areas & in close proximity to Bald Eagle Roost site. Location is approximately 99 yards from Porcupine Creek.**

**Section/Township/Range: 26 6S94W**

**Storm water Management and Erosion control**  
**Location Name: TEP Rocky Mountain LLC Juhan Tank facility**  
**Facility ID # 479723**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**

**Storm water Management and Erosion control**  
**Location Name: TEP Rocky Mountain LLC Juhan Tank facility**  
**Facility ID # 479723**



**Photo # 2054 Berm/BMP needs maintenance, berm breached/eroded & sediment is being transported off location into a vegetated area. (near NW corner of location)**



**Photo # 2055 Berm/BMP needs maintenance, berm breached/eroded & sediment is being transported off location into a vegetated area. (near NW corner of location)**

**Storm water Management and Erosion control**  
**Location Name: TEP Rocky Mountain LLC Juhan Tank facility**  
**Facility ID # 479723**



**Photo # 2056 Berm/BMP needs maintenance, berm breached/eroded & sediment is being transported off location into a vegetated area. (Berm on north side of location)**

**Photo # 2057 Berm/BMP needs maintenance, berm breached/eroded & sediment is being transported off location into a vegetated area. (Berm on north side of location)**

**Storm water Management and Erosion control**  
**Location Name: TEP Rocky Mountain LLC Juhan Tank facility**  
**Facility ID # 479723**



**Photo # 2058 Failure to maintain chemical BMP/chemical containment approximately 3/4 full of fluid/BMP insufficient to contain possible spill.**