

Interim Reclamation and Stormwater Inspection

Date: 03/20/2024

Operator: WESTERN OPERATING COMPANY - 95620

Location ID: 312229

Inspection Document #: 708201016

Logan County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Photo 1. Stained soil observed at tank battery loadout line.

Inspection Photos
Location Name: Propst B3X
Location ID: 312229



Photo 2. Trash observed southeast of tank battery.

Inspection Photos
Location Name: Propst B3X
Location ID: 312229



Photo 3. Straw wattle BMP does not appear to be properly installed via good engineering practices (e.g. trenched and backfilled).

Inspection Photos
Location Name: Propst B3X
Location ID: 312229



Photo 4. Erosion degradation occurring alongside the access road leading to well API 075-06964.

Inspection Photos
Location Name: Propst B3X
Location ID: 312229



Photo 5. Taken west of the tank battery; see comments in Photos 3 & 4 for additional.



Photo 6. Erosion degradation occurring north of the meter shed. No visible stormwater control measures observed.



Photo 7. Evidence of sediment deposition occurring north of the meter shed.

Inspection Photos
Location Name: Propst B3X
Location ID: 312229



Photo 8. Weed debris accumulations within the pit do not appear to have been removed since documented on previous inspections.

Inspection Photos
Location Name: Propst B3X
Location ID: 312229



Photo 9. Evidence of sediment deposition resulting from erosion from within the pit area. No apparent stormwater control measures observed during this inspection.

Inspection Photos
Location Name: Propst B3X
Location ID: 312229



Photo 10. Debris (plastic piping) and erosion degradation within the pit area, illustrated by red arrows. Also pictured (green arrow) NFPA placard installed at vertical separator.

Inspection Photos
Location Name: Propst B3X
Location ID: 312229



Photo 11. Stained soils appear to have been removed at pumpjack exhaust.



Photo 12. Stained soils at wellhead appear to have been removed.