

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403711993

Date Received:

04/01/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 708901792

Inspection Date: 09/25/2023

FIR Submit Date: 09/26/2023

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 334815

Location Name: FNB OF GRAND JUNCTION Number: 36NWSE County: _____
TR-66S95W

Qtrqtr: NWSE Sec: 36 Twp: 6S Range: 95W Meridian: 6

Latitude: 39.478619 Longitude: -107.943411

FACILITY - API Number: 05-045- -00 Facility ID: 334815

Facility Name: FNB OF GRAND JUNCTION Number: 36NWSE
TR-66S95W

Qtrqtr: NWSE Sec: 36 Twp: 6S Range: 95W Meridian: 6

Latitude: 39.478619 Longitude: -107.943411

CORRECTIVE ACTIONS:

1 ☒ CA# 182180

Corrective Action: Remove and properly dispose of all stained soils and gravel.

Date: 10/06/2023

Response: CA COMPLETED

Date of Completion: 10/19/2023

Operator Comment: Stained soil has been removed and properly disposed of. Corrective Action complete.

COGCC Decision: Approved pending re-inspection

COGCC Representative:			
2	✔	CA# 182181	
Corrective Action:	Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved.		Date: <u>10/11/2023</u>
Response:	<u>CA COMPLETED</u>		Date of Completion: <u>11/21/2023</u>
Operator Comment:	Rip Rap has been repaired. Corrective Action complete.		
COGCC Decision:	<u>Approved pending re-inspection</u>		
COGCC Representative:			

OPERATOR COMMENT AND SUBMITTAL	
Comment:	CA#182180: Stained soil has been removed and properly disposed of. Corrective Action complete. CA#182181: Rip Rap has been repaired. Corrective Action complete.
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: <u>Jordan Veith</u>	Signed: _____
Title: <u>TEP Representative</u>	Date: <u>4/1/2024 3:49:03 PM</u>

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403711993	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files