

FORM 6 <small>Rev 11/20</small>	State of Colorado Energy & Carbon Management Commission <small>1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109</small>				<table border="1" style="width:100%; border-collapse: collapse;"><tr><td style="width:12.5%; text-align: center;">DE</td><td style="width:12.5%; text-align: center;">ET</td><td style="width:12.5%; text-align: center;">OE</td><td style="width:12.5%; text-align: center;">ES</td></tr></table>				DE	ET	OE	ES																																									
	DE	ET	OE	ES																																																	
	WELL ABANDONMENT REPORT				Document Number: 403742597 Date Received: 																																																
<p>This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.</p> <p>A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.</p>																																																					
<table style="width:100%;"><tr><td colspan="3">ECMC Operator Number: 47120</td><td colspan="3">Contact Name: Lorena Ruiz</td></tr><tr><td colspan="3">Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP</td><td colspan="3">Phone: (970) 336-3535</td></tr><tr><td colspan="3">Address: P O BOX 173779</td><td colspan="3">Fax:</td></tr><tr><td>City: DENVER</td><td>State: CO</td><td>Zip: 80217-</td><td colspan="3">Email: lorena_ruiz@oxy.com</td></tr><tr><td colspan="3">For "Intent" 24 hour notice required,</td><td colspan="2">Name: Revas, Robbie</td><td>Tel: (720) 661-7242</td></tr><tr><td colspan="3">ECMC contact:</td><td colspan="3">Email: robbie.revas@state.co.us</td></tr></table>						ECMC Operator Number: 47120			Contact Name: Lorena Ruiz			Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP			Phone: (970) 336-3535			Address: P O BOX 173779			Fax:			City: DENVER	State: CO	Zip: 80217-	Email: lorena_ruiz@oxy.com			For "Intent" 24 hour notice required,			Name: Revas, Robbie		Tel: (720) 661-7242	ECMC contact:			Email: robbie.revas@state.co.us														
ECMC Operator Number: 47120			Contact Name: Lorena Ruiz																																																		
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP			Phone: (970) 336-3535																																																		
Address: P O BOX 173779			Fax:																																																		
City: DENVER	State: CO	Zip: 80217-	Email: lorena_ruiz@oxy.com																																																		
For "Intent" 24 hour notice required,			Name: Revas, Robbie		Tel: (720) 661-7242																																																
ECMC contact:			Email: robbie.revas@state.co.us																																																		
Type of Well Abandonment Report: <input checked="" type="checkbox"/> Notice of Intent to Abandon <input type="checkbox"/> Subsequent Report of Abandonment																																																					
<table style="width:100%;"><tr><td colspan="2">API Number 05-123-21036-00</td><td colspan="4">Well Number: 4-23A</td></tr><tr><td>Well Name: BERNHARD</td><td colspan="5"></td></tr><tr><td>Location: QtrQtr: NWNW Section: 23 Township: 2N Range: 67W Meridian: 6</td><td colspan="5"></td></tr><tr><td>County: WELD</td><td colspan="5">Federal, Indian or State Lease Number:</td></tr><tr><td>Field Name: WATTENBERG</td><td colspan="5">Field Number: 90750</td></tr></table>						API Number 05-123-21036-00		Well Number: 4-23A				Well Name: BERNHARD						Location: QtrQtr: NWNW Section: 23 Township: 2N Range: 67W Meridian: 6						County: WELD	Federal, Indian or State Lease Number:					Field Name: WATTENBERG	Field Number: 90750																						
API Number 05-123-21036-00		Well Number: 4-23A																																																			
Well Name: BERNHARD																																																					
Location: QtrQtr: NWNW Section: 23 Township: 2N Range: 67W Meridian: 6																																																					
County: WELD	Federal, Indian or State Lease Number:																																																				
Field Name: WATTENBERG	Field Number: 90750																																																				
<i>Only Complete the Following Background Information for Intent to Abandon</i>																																																					
<table style="width:100%;"><tr><td>Latitude: 40.129130</td><td colspan="2">Longitude: -104.865150</td><td colspan="3"></td></tr><tr><td>GPS Data: GPS Quality Value: 2.4</td><td>Type of GPS Quality Value:</td><td colspan="4">Date of Measurement: 09/12/2006</td></tr><tr><td colspan="6">Reason for Abandonment: <input type="checkbox"/> Dry <input checked="" type="checkbox"/> Production Sub-economic <input type="checkbox"/> Mechanical Problems</td></tr><tr><td colspan="6"><input type="checkbox"/> Other</td></tr><tr><td colspan="2">Casing to be pulled: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</td><td colspan="4">Estimated Depth: 1550</td></tr><tr><td colspan="2">Fish in Hole: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</td><td colspan="4">If yes, explain details below</td></tr><tr><td colspan="2">Wellbore has Uncemented Casing leaks: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</td><td colspan="4">If yes, explain details below</td></tr><tr><td colspan="6">Details:</td></tr></table>						Latitude: 40.129130	Longitude: -104.865150					GPS Data: GPS Quality Value: 2.4	Type of GPS Quality Value:	Date of Measurement: 09/12/2006				Reason for Abandonment: <input type="checkbox"/> Dry <input checked="" type="checkbox"/> Production Sub-economic <input type="checkbox"/> Mechanical Problems						<input type="checkbox"/> Other						Casing to be pulled: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		Estimated Depth: 1550				Fish in Hole: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		If yes, explain details below				Wellbore has Uncemented Casing leaks: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		If yes, explain details below				Details:					
Latitude: 40.129130	Longitude: -104.865150																																																				
GPS Data: GPS Quality Value: 2.4	Type of GPS Quality Value:	Date of Measurement: 09/12/2006																																																			
Reason for Abandonment: <input type="checkbox"/> Dry <input checked="" type="checkbox"/> Production Sub-economic <input type="checkbox"/> Mechanical Problems																																																					
<input type="checkbox"/> Other																																																					
Casing to be pulled: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		Estimated Depth: 1550																																																			
Fish in Hole: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		If yes, explain details below																																																			
Wellbore has Uncemented Casing leaks: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		If yes, explain details below																																																			
Details:																																																					
Current and Previously Abandoned Zones																																																					
<table style="width:100%;"><tr><th>Formation</th><th>Perf. Top</th><th>Perf. Btm</th><th>Abandoned Date</th><th>Method of Isolation</th><th>Plug Depth</th></tr><tr><td>J SAND</td><td>8004</td><td>8030</td><td></td><td></td><td></td></tr></table> <p>Total: 1 zone(s)</p>						Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth	J SAND	8004	8030																																							
Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth																																																
J SAND	8004	8030																																																			
Casing History																																																					
<table style="width:100%;"><tr><th>Casing Type</th><th>Size of Hole</th><th>Size of Casing</th><th>Grade</th><th>Wt/Ft</th><th>Csg/Liner Top</th><th>Setting Depth</th><th>Sacks Cmt</th><th>Cmt Btm</th><th>Cmt Top</th><th>Status</th></tr><tr><td>SURF</td><td>12+1/4</td><td>8+5/8</td><td>J-55</td><td>24</td><td>0</td><td>666</td><td>280</td><td>666</td><td>0</td><td>VISU</td></tr><tr><td>1ST</td><td>7+7/8</td><td>4+1/2</td><td>I-80</td><td>11.6</td><td>0</td><td>8173</td><td>515</td><td>8173</td><td>3890</td><td>CBL</td></tr></table>						Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status	SURF	12+1/4	8+5/8	J-55	24	0	666	280	666	0	VISU	1ST	7+7/8	4+1/2	I-80	11.6	0	8173	515	8173	3890	CBL															
Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status																																											
SURF	12+1/4	8+5/8	J-55	24	0	666	280	666	0	VISU																																											
1ST	7+7/8	4+1/2	I-80	11.6	0	8173	515	8173	3890	CBL																																											

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7950 with 2 sacks cmt on top. CIBP #2: Depth 300 with 90 sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 5 sks cmt from 7270 ft. to 7210 ft. Plug Type: CASING Plug Tagged: ☐
Set 5 sks cmt from 4450 ft. to 4390 ft. Plug Type: CASING Plug Tagged: ☐
Set 40 sks cmt from 2400 ft. to 1900 ft. Plug Type: CASING Plug Tagged: ☐
Set 90 sks cmt from 300 ft. to 0 ft. Plug Type: CASING Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at 7300 ft. with 95 sacks. Leave at least 100 ft. in casing 7270 CICR Depth

Perforate and squeeze at 4480 ft. with 95 sacks. Leave at least 100 ft. in casing 4450 CICR Depth

Perforate and squeeze at 2400 ft. with 120 sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 385 sacks half in. half out surface casing from 1600 ft. to 616 ft. Plug Tagged: ☐

Set 90 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☒ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing

Surface Plug Setting Date: _____ Cut and Cap Date: _____ Number of Days from Setting Surface Plug to Capping or Sealing the Well: _____

*Wireline Contractor: _____

*Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

Signage for P&As:

Prior to commencing operations, KMG will post signs in conspicuous locations. The signs will indicate plugging and abandonment operations are being conducted, the well name, well, and the Operator's contact information. Signs will be placed so as not to create a potential traffic hazard.

Notifications:

Courtesy notifications will be sent to all parcel owners with building units within 1,500 feet of the location letting them know about out plugging and abandonment operations and providing contact information for Kerr McGee's response line and online resources.

Wellbore Pressure:

In some cases, wellbore pressure drawdown operations may occur approximately 1-2 days prior to Move In Rig Up (MIRU) of the workover rig. This is conducted to allow for reduced time that the workover rig is needed on location. These operations will be conducted in accordance with Form 4 and/or Form 6 requirements.

Water:

Water will be placed on dirt access roads to mitigate dust as needed.

Lighting:

Operations are daylight-only; no lighting impacts are anticipated from operations.

Noise:

Operations will be in compliance with Table 423-1 requirements. Based off the rig sound signature, rig orientation will be considered to reduce noise levels to nearby building units.

Environmental Concerns:

This location was reviewed using a desktop method to review publicly available wildlife data (including CPW & ECMC data) as well as internal wildlife datasets and aerial imagery. All field personnel are trained to identify wildlife risks and raise concerns noticed during operations with the KMOG Health, Safety, and Environment (HSE) department.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Lorena Ruiz
Title: Regulatory Tech Date: _____ Email: lorena_ruiz@oxy.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

ECMC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: _____

<u>COA Type</u>	<u>Description</u>
0 COA	

Attachment List

<u>Att Doc Num</u>	<u>Name</u>
403742611	WELLBORE DIAGRAM
403742613	PROPOSED PLUGGING PROCEDURE

Total Attach: 2 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)