



99999999

OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT

| | | | | |
|---|------------------|--|---|---|
| <input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION | | | 1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100 | |
| <input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION | | | | |
| API No. 05- 123 - 14688 | | LEASE NAME: Concord State A 1 | | |
| LOCATION: NW 32 16 - 9N - 56 | | OPERATOR: Gear | | |
| DATE: 11-16-95 | | INSPECTOR: Ed Binkley (EBB) | | |
| Insp. Type: SR | Insp. Status: 2A | PA: <input checked="" type="radio"/> Y <input type="radio"/> N | Pass/Fail: <input checked="" type="radio"/> P <input type="radio"/> F | Viol.: Y <input checked="" type="radio"/> N |

| INSPECTION ITEM | COMMENTS | INPUT |
|--|-----------|-------|
| Well ID Signs (Rule 210) | | |
| Pits (Reserve/Production) (Rule 902, 903, 904) | | |
| Fences (Rule 604.C.(3), 1003.A) | | |
| Tank Battery Equipment (Rule 604) | | |
| Fire Walls/Berms/Dikes (Rule 604) | | |
| General Housekeeping (Rule 603.G) | | |
| Spills (Oil/Water) (Rule 908) | | |
| Bradenhead (Rule 207) | | |
| Drilling Well/Workover (Rule 315) | | |
| Surface Rehabilitation (Rule 317) | grassland | |
| Miscellaneous | | |

CORRECTIVE ACTION REQUIRED:



00264892

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site

NOV 21 1995

OIL & GAS CONSERVATION COMMISSION

Dave Banko 826-4480 called
11-4-90 - He was consultant to
Concord Oil on the Concord St. A
#1 NWSW16-9N-56W. Well reached
TD 8-22-90. Concord has stopped
returning Mr. Banko's calls and
he thought we should know.

Bob V.

11-30-90 Well has tubing and 2"
valve. No recent activity as of
today.

4/26/91 Spoke to Mark @ Geor. Dtg.
Bob was to call