

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Webster Compressor Station

Facility ID: 465894



Photo # 2444 From entrance to location



Photo # 2445 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Webster Compressor Station

Facility ID: 465894



Photo # 2446 Location



Photo # 2447 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Webster Compressor Station

Facility ID: 465894



Photo # 2448 Location



Photo # 2449 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Webster Compressor Station

Facility ID: 465894



Photo # 2450 Location



Photo # 2451 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Webster Compressor Station

Facility ID: 465894



Photo # 2452 Location



Photo # 2453 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Webster Compressor Station

Facility ID: 465894



Photo # 2454 Tank battery lacks required signage



Photo # 2455 Open ended load line

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Webster Compressor Station

Facility ID: 465894



**Photo # 2456 Compressor line lacks wildlife protection /wildlife hazard/available for entry by wildlife**



**Photo # 2457 Some required info on antifreeze tank is illegible**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Webster Compressor Station

Facility ID: 465894



**Photo # 2458 Openings on vessel available for entry by wildlife/wildlife hazards**



**Photo # 2459 Openings on vessel available for entry by wildlife/wildlife hazards**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Webster Compressor Station

Facility ID: 465894



Photo # 2460 Debris