

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 24-26 Pad
Location ID: 324192



**Location Overview: Location is within High Priority/Density
Habitat areas.**

Section/Township/Range: 26 6S95W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 24-26 Pad
Location ID: 324192



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 24-26 Pad
Location ID: 324192



Photo # 3464 Tunnel erosion in ditch/BMP needs maintenance (ditch is near sediment trap along lease road approximately 70 yards from entrance to location)



Photo # 3465 Tunnel erosion in ditch/BMP needs maintenance (ditch is near sediment trap along lease road approximately 70 yards from entrance to location)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PA 24-26 Pad
Location ID: 324192



Photo # 3466 Rip Rap/BMP on sediment trap inlet needs maintenance - stormwater is cutting/eroding around edge of Rip Rap. (N/NW area of location)



Photo # 3467 Rip Rap/BMP on sediment trap inlet needs maintenance - stormwater is cutting/eroding around edge of Rip Rap. (N/NW area of location)